

LABOUR		
1	To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	\$ 80.00
2	To remove, reinstall tailgate windscreen	\$ 150.00
3	To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	\$ 100.00
4	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	\$ 1,000.00
5	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	\$ 1,000.00
6	To apply anti-rust chemical on repaired and replaced panel.	\$ 120.00
7	To remove, reinstall tailgate mechanism and check for function	\$ 80.00
Labour total		\$ 2,530.00
Parts & Labour total		\$ 7,315.40