

Attn: Kenneth

Cheng Hoe Motor Pte Ltd

Bldg 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chnhmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBB3877H
TP/CHINA

Not with work
11/10/2024 8:3450

M/S: CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111
ATTN: Motor Claim Department
WS Ref: TP/CHINA
Claim Type: Third Party
Accident Date: 13/07/2024
TP Veh Reg No: SLD8885Y

FAX: 62221033 6day

Claim No: ES2400584
Estimate No: ES2400584/WL
Date: 16 Jul 2024
Policy No: 5118146709-03
Veh Reg No: GBB3877H
Make/Model: TOYOTA DYNA 150 D
Chassis No: JTFAT35Y80K200356
Engine No: 1KD1906849
Reg. Date: 12/02/2009

Estimate Repair Cost to Vehicle No : GBB3877H

Pages: 1/1

Description	U/Price	Quantity	Cost	Amount
Cost Plus			SS	SS
1 FRONT BUMPER	170.00	1 PC	170.00	✓
2 FRONT GRILLE	180.00	1 PC	180.00	✓
3 FRONT GRILLE LOGO	85.00	1 PC	85.00	✓
4 FRONT GRILLE CLIP	3.50	4 PC	14.00	✓
5 HEADLAMP RH	320.00	1 PC	320.00	✓
6 FRONT PANEL	400.00	1 PC	400.00	✓
7 FRONT PANEL EMBLEM	40.00	1 PC	40.00	✓
8 FRONT WINDSCREEN GLASS RUBBER	90.00	1 PC	90.00	✓
9 FRONT RH DOOR	680.00	1 PC	680.00	✓
			1,979.00	
	Add 10%		197.90	2,176.90
Special Net				
10 FRONT NUMBER PLATE	20.00	1 PC	20.00	✓
11 FRONT RH DOOR COMPANY STICKER	20.00	1 PC	20.00	✓
				40.00
Labour				
12 REMOVE & REFIX DASHBOARD, METER ASSY & CHECK WIRING	280.00	1 LA	280.00	250
13 REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL	100.00	1 LA	100.00	✓
14 REMOVE AND REFIX FRONT WINDSCREEN GLASS	60.00	1 LA	60.00	✓
15 REMOVE & REFIX FRT BUMPER	900.00	1 LA	900.00	700
ASSY, GRILLE, HEADLAMPS, FRT RH DOOR & ATTACHMENTS, TO RENEW FRT PANEL & REALIGN THE				
16 PUTTY & RESPRAY ON FRT BUMPER, FRT PANEL, FRT GRILLE, FRT RH DOOR	750.00	1 LA	750.00	700
17 REMOVE & REFIX FRT RH DOOR GLASS	60.00	1 LA	60.00	✓
18 RUSTPROOFING	60.00	1 LA	60.00	✓
				2,210.00

Parts \$1979
Add supp 120
\$2099
add 10% 209.90
\$2308.90
SN 40.00
lab 1930.00
Supp lab 80.00
\$4358.90

Total SS 4,426.90
Add GST @ 9% 398.42
Total Amount payable SS 4,825.32

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE



Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Suppl

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62221033

ATTN: Motor Claim Department

WS Ref: TP/CHINA

Claim Type: Third Party

Accident Date: 13/07/2024

TP Veh Reg No: SLD8885Y

Claim No: ES2400584

Estimate No: ES2400584/WL

Date: 19 Jul 2024

Policy No: 5118146709-03

Veh Reg No: GBB3877H

Make/Model: TOYOTA DYNA 150 D

Chassis No: JTFAT35Y80K200356

Engine No: 1KD1906849

Reg. Date: 12/02/2009

Estimate Repair Cost to Vehicle No : GBB3877H

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
Cost Plus				
1 FRONT RH STEP GARNISH	120.00	1 PC <i>CM</i>	120.00	✓
			120.00	
	Add 10%		12.00	132.00
Labour				
2 TO REWRITE ADVERTISEMENT	80.00	1 PC <i>na</i>	80.00	✓
				80.00

Total	S\$ 212.00
GST Amount	S\$ 19.08
Total Amount payable	<u>S\$ 231.08</u>

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE