



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 1422Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	300 STICKER	NECESSARY	40.00	40.00
1	FRONT BUMPER	CRACKED	420.00	420.00
1	HINO STICKER	NECESSARY	40.00	40.00
1	R/DOOR FRAME TRIM	MISSING	65.00	65.00
1	R/DOOR MIRROR ASSY	MISSING	550.00	550.00
1	R/END MOULDING	DENTED / CUT	195.00	195.00
1	R/EURO 6 STICKER	NECESSARY	50.00	50.00
1	R/F BUMPER BRACKET	* CHECK	195.00	-
1	R/F DOOR SIGNAL LAMP	BROKEN	50.00	50.00
1	R/F DOOR WINDOW	SHATTERED	300.00	300.00
1	R/F FOG LAMP	MTG BENT	200.00	200.00
1	R/F INNER SILL MLDG	DISTORTED	120.00	120.00
1	R/F LOWER DOOR HINGE	BENT	70.00	70.00
1	R/F STEP	BROKEN	180.00	180.00
1	R/F UPPER DOOR HINGE	BENT	35.00	35.00
1	R/F WINDOW REGULATOR	BENT	100.00	100.00
1	R/INN DOOR LOCK	DENTED	150.00	150.00
1	R/OUTER A-PILLAR	BENT	300.00	300.00
1	R/O WIND GLASS SEAL	CUT	45.00	45.00
1	R/WIPER ARM CAP	MISSING	7.00	7.00
1	RH 616 STICKER	NECESSARY	50.00	50.00
1	RIGHT FRONT DOOR	BENT	950.00	950.00
1	RIGHT HEADLAMP ASSY	BROKEN	420.00	420.00
1	WINDSCREEN	CRACKED	850.00	850.00
1	WINDSCREEN SEAL	CUT	85.00	85.00
			5,467.00	5,272.00
	<u>SPECIAL NETT ITEMS</u>			
1	IU BRACKET (SN)	NECESSARY	15.00	15.00
			15.00	15.00

Report Ref No. CS/CTI24060058/Knce2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TOTAL 221.0 WU X 42.00 SGD/H.		928.20	928.20
	LABOUR COST 102.0 WU X 42.00 SGD/H.		428.40	428.40
	MATERIAL COST.		168.90	168.90
			1,525.50	1,525.50
	GRAND TOTAL		7,007.50	6,812.50
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$195.00 NETT)			6,812.50

Report Ref No. CS/CTI24060058/Knce2(N)

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.