

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

|  |  | Affiliated to Federation Internati  | onale Des Experts En | Automobile          |
|--|--|-------------------------------------|----------------------|---------------------|
| MS   | INCOME INSURA  | NCE LTD                             | Ref:                 | CS/INC24070267/Uvh3 |
|  | 75 BRAS BASAH  | -                                   | Date:                | 16/07/2024          |
|  | INCOME CENTRE  | SINGAPORE 189557                    | Code:                | INC                 |
| 1. Policy Particulars :- THIRD PARTY CLAIM   |  |                                     |                      |                     |
|  | Insured Veh.   | SHD 9500Z                           | Veh. Inspected       | SNB 7328H           |
|  | Policy No.   | -                                   | Coverage             | 0                   |
|  | Claim No.  | MT/1286215-002                      | Excess               | \$0.00              |
|  | Assign From  | CHARLOTTE CHEW                      | Assign Date          | 16/07/2024          |
| 2. Vehicle Details   |  |                                     |                      |                     |
|  | Make & Model   | TOYOTA COROLLA SPORTS<br>HYBRID (A) | C.C                  | 1797                |
|  | Engine No.   | 2ZR2D06203                          | Year of Reg.         | 10/09/2021          |
|  | Chassis No.  | ZWE2111015588                       | Colour               | SILVER              |
|  | Odometer   | 178588 KM                           | Steering             | IN ORDER            |
|  | Brakes   | IN ORDER                            | General              | GOOD                |
|  | Modification(s)  | RIMS: SPORTS RIM                    |                      |                     |
| 3.   | Conditions of Tyres  |                                     |                      |                     |
|  |  | Size                                | Make                 | Balance (mm)        |
|  | R/H Front Tyre   | 205/55R16                           | ECORUN               | 5                   |
|  | L/H Front Tyre   | 205/55R16                           | ECORUN               | 5                   |
|  | R/H Rear Tyre  | 205/55R16                           | ECORUN               | 5                   |
|  | L/H Rear Tyre  | 205/55R16                           | ECORUN               | 5                   |
| 4. Description of Damages  |  |                                     |                      |                     |
| ГНЕ  | VEHICLE SUSTAI   | NED DAMAGES AT THE N/S BODY.        |                      |                     |
| DAN  | IAGES SEE DETAI  | LS.                                 |                      |                     |
| 5. General Information   |  |                                     |                      |                     |
|  | Accident Date  | 13/07/2024                          | Inspection Date      | 16/07/2024 (14:11)  |
|  | Survey held at CARSMITH PTE LTD - 8 KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875 |                                     |                      |                     |
| 5a.  | Remarks  |                                     |                      |                     |
| A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                                     |                      |                     |
| 5b. Estimate Days of Repair  |  |                                     |                      |                     |

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days