



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLQ 9219X

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR FENDER RH	DENTED	\$1,985.00	\$1,985.00
1	REAR FENDER GLASS C/W MOULDING RH	NECESSARY	\$400.00	\$125.00
1	REAR FENDER AIR VENT RH	NOT NECESSARY	\$138.00	\$0.00
1	REAR FENDER AIR VENT PANEL RH	NOT NECESSARY	\$572.00	\$0.00
1	REAR FENDER INNER COWLING RH	TORN	\$385.00	\$240.00
1	REAR ABS SENSOR	NOT NECESSARY	\$153.00	\$0.00
1	REAR SHOCK ABSORBER RH	NOT NECESSARY	\$475.00	\$0.00
1	REAR LOWER ARM RH	NOT NECESSARY	\$578.00	\$0.00
1	REAR KNUCKLE ARM RH	NOT NECESSARY	\$760.00	\$0.00
1	REAR WHEEL HUB WITH BEARING RH	NOT NECESSARY	\$465.00	\$0.00
1	REAR UPPER ARM RH	NOT NECESSARY	\$250.00	\$0.00
1	REAR ADJUSTABLE ARM RH	NOT NECESSARY	\$189.00	\$0.00
1	REAR CONTROL ARM RH	NOT NECESSARY	\$238.00	\$0.00
1	REAR LINKAGE	NOT NECESSARY	\$210.00	\$0.00
1	REAR BUMPER	TORN	\$1,684.00	\$1,390.00
1	REAR BUMPER INNER SIDE GARNISH RH	NOT NECESSARY	\$286.00	\$0.00
2	REAR BUMPER SIDE RETAINER @\$74.00	NOT NECESSARY	\$148.00	\$0.00
2	REAR BUMPER BRACKET @\$65.00	NOT NECESSARY	\$130.00	\$0.00
1	REVERSE SENSOR RH	NOT NECESSARY	\$408.00	\$0.00
6	REVERSE SENSOR HOLDER @\$64.00	NOT NECESSARY	\$384.00	\$0.00
1	TAILLAMP RH	NOT NECESSARY	\$736.00	\$0.00
	LESS 10.00% DISCOUNT		(\$1,057.40)	(\$374.00)
			\$9,516.60	\$3,366.00

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SIDE SKIRT CLIP RH (SN)	NOT NECESSARY	\$60.00	\$0.00
1	REAR FENDER SEALANT RH (SN)	NECESSARY	\$80.00	\$60.00
1	SET REAR FENDER TOP GARNISH CLIP (SN)	NOT NECESSARY	\$40.00	\$0.00
1	SET REAR FENDER COWLING CLIP (SN)	NECESSARY	\$80.00	\$30.00
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	\$80.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR FENDER GLASS SEALANT RH (SN)	NECESSARY	\$100.00	\$40.00
1	SET TAILLAMP CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	\$150.00	\$0.00
1	REAR WHEEL SPORT RIM (SN)	CUT	\$1,800.00	\$680.00
1	REAR WHEEL TYRE (SN)	NOT NECESSARY	\$480.00	\$0.00
1	BRAKE OIL (SN)	NOT NECESSARY	\$80.00	\$0.00
			\$3,000.00	\$810.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING, REMOVAL AND REPLACING PARTS		\$1,800.00	\$600.00
	TO SPRAY PAINT AFFECTED AREA		\$1,800.00	\$400.00
	TUFF COAT		\$350.00	\$40.00
	WIRING CHECK		\$380.00	\$30.00
	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR		\$250.00	\$60.00
	REMOVE AND REFIX REAR UNDERCARRIAGE	NOT NECESSARY	\$1,200.00	\$0.00
	TO PRESS REAR WHEEL BEARING	NOT NECESSARY	\$80.00	\$0.00
	FOUR WHEEL ALIGNMENT		\$120.00	\$80.00
	CONDUCT WATER LEAKAGE TEST	NOT NECESSARY	\$100.00	\$0.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING		\$250.00	\$50.00
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC		\$550.00	\$150.00
			\$6,880.00	\$1,410.00

GRAND TOTAL			\$19,396.60	\$5,586.00
--------------------	--	--	--------------------	-------------------

	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$4,450.00
--	---	--	--	-------------------

Report Ref No: CS/INC24070270/Avh3e2				
---	--	--	--	--

TOTAL FOR SPARE PARTS: \$ 12,516.60 \$ 4,176.00
TOTAL FOR LABOUR : \$ 6,880.00 \$ 1,410.00
TOTAL REPAIR COST: \$ 19,396.60 \$ 5,586.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.