



Kenrick
17/7/24

NOT Authash
Murray B & Pain
Ex TBA

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

3328.00 4 days

Attention To : ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Claim Details

Case Ref. No. : OD/072024/7509
Date : 15-07-2024
Accident Date : 15-07-2024

Vehicle Details

Make & Model : Mazda MAZDA3 4-DOOR SEDAN
1.5L SP.6EAT
Chassis No : JM6BM42A8G0326560
Registration No : SLP7935E

S/N	Description	Qty	Amount (\$)
1	RH HEADLAMP	1.00	Bro \$1,300.00 ✓
2	FRONT BUMPER	1.00	Bu/Dr \$480.00 ✓
3	FRONT BUMPER RH NOZZIE GUN	1.00	CM \$140.00 ✓
4	FRONT BUMPER RH NOZZIE GUN COVER	1.00	mi \$60.00 ✓
5	FRONT BUMPER RH SIGNAL LIGHT	1.00	pu \$90.00 X
6	FRONT BUMPER RH FOG LAMP	1.00	pu \$200.00 X
7	FRONT BUMPER RH FOG LAMP COVER	1.00	hy \$30.00 ✓
8	FRONT BUMPER RH SIDE RETAINER	1.00	mi \$10.00 ✓
9	FRONT BUMPER REINFORCEMENT	1.00	re \$270.00 X
10	FRONT BUMPER CLIPS	10.00	re \$20.00 ✓
11	WIPER TANK	1.00	nd \$60.00 ✓
12	WIPER TANK CAP	1.00	(mi) \$20.00 X
13	FRONT RH FENDER	1.00	Bu \$180.00 ✓
			\$2,860.00
Margin: 10%			\$286.00
			\$3,146.00
14	TO RESET HEADLAMP SYSTEM	1.00	\$280.00 20h
15	TO REPAIR DAMAGES	1.00	\$580.00 400h
16	TO SPRAY PAINTING	1.00	\$680.00 400h

Subtotal w/o GST:

\$4,686.00

Issued by Yee Shu Yaw

This is a computer-generated document. No signature is required.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: