

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 17 Jul 2024

Preliminary Advice

Vehicle No	: SLP7935E	Accident Date	: 15/07/2024
Make	: MAZDA 3	Policy No.	: MPC24A00044600
Assignment Date	: 17/07/2024	Excess	: S\$0.00
Date of Inspection	: 17/07/2024	Est. Duration of Repair	: 4
Inspection At	: VIN'S MOTOR PTE LTD (SIN MING) 20 SIN MING LANE, #06-65 MIDVIEW CITY SINGAPORE 573968		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,686.00
Revised Amount	:S\$	3,088.00
Check Items (Estimated)	:S\$	599.00
Total	:S\$	3,687.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	25,000.00
COE / PARF Rebate	:S\$	14,045.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,955.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : THE VEHICLE REPAIR ON PART BY PART BASIS DUE TO NO 2ND HAND PARTS AVAILABLE.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.