



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24060059/Anh3
16 RAFFLES QUAY	Date:	30/09/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 3254Z	Veh. Inspected	SNQ 8131Y
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24005173MFCT	Excess	\$0.00
Assign From	CAROLINE CABRERA	Assign Date	12/06/2024

2. Vehicle Details

Make & Model	TOYOTA NOAH HYBRID	C.C	1797
Engine No.	2ZR2X28635	Year of Reg.	09/05/2024
Chassis No.	ZWR900122112	Colour	BLACK
Odometer	5685 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60R16	TOYO	6
L/H Front Tyre	205/60R16	TOYO	6
R/H Rear Tyre	205/60R16	TOYO	6
L/H Rear Tyre	205/60R16	TOYO	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/06/2024	Inspection Date	11/06/2024
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days