

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MY AUTO LEASING PTE LTD
397 JOO CHIAT ROAD
SINGAPORE 427628

Contact : 82687588 89498320

TP 1st Cap.
Hui Rong.

TAX INVOICE

Repair Code : CLM17947

Date in : 10/06/2024

Vehicle Num. : SNQ8131Y

Model : TOYOTA NOAH HYBRID 1.8X CVT

Chassis/Eng# : ZWR900122112/2ZR2X28635

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>2ehnd</i>	1	797.00	✓ 797.00
REAR BUMPER REFLECTOR L/R <i>2en</i>	2	52.00	+ 104.00
REAR BUMPER REVERSE SENSOR <i>1 piece dng d</i>	4	286.90	286.90 1147.60
REAR BUMPER REVERSE SENSOR 'O' RING <i>1 piece m</i>	4	38.20	38.20 152.80
REAR BUMPER REVERSE SENSOR HOLDER <i>m</i>	4	51.40	100 205.60
REAR BUMPER SIDE RETAINER L/R <i>pen</i>	2	119.10	+ 238.20
REAR END PANEL <i>Dented</i>	1	916.00	795 916.00
REAR END PANEL ANTENNA SENSOR <i>pen</i>	1	76.30	+ 76.30
REAR END PANEL INNER TOP GARNISH <i>Dehnd</i>	1	207.10	1812 207.10
REAR TAILGATE <i>Dented</i>	1	2719.30	2719.30
REAR TAILGATE 'HYBRID' EMBLEM <i>en</i>	1	92.70	✓ 92.70
REAR TAILGATE DAMPER L/R <i>3en</i>	2	395.00	+ 790.00
REAR TAILGATE HINGES L/R	2	72.20	+ 144.40
REAR TAILGATE INNER PULL HANDLE	1	24.90	+ 24.90
REAR TAILGATE INNER RUBBER STOPPER L/R <i>3en</i>	2	67.80	+ 135.60
REAR TAILGATE INNER SIDE RUBBER MOULDING L/R	2	37.00	+ 74.00
REAR TAILGATE INNER TRIM BOARD <i>enhd</i>	1	870.90	740 870.90
REAR TAILGATE MECHANISM LOCK <i>hd</i>	1	495.40	350 495.40

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MY AUTO LEASING PTE LTD
 397 JOO CHIAT ROAD
 SINGAPORE 427628

Contact : 82687588 89498320

TAX INVOICE

Repair Code : CLM17947
 Date in : 10/06/2024
 Vehicle Num. : SNQ8131Y
 Model : TOYOTA NOAH HYBRID 1.8X CVT
 Chassis/Eng# : ZWR900122112/2ZR2X28635

REAR TAILGATE WINDSCREEN MOULDING	1	41.90	✓	41.90
Subtotal before discount				9,233.70
Percentage discount 25%				2,308.43
Sub-total 1				6,925.28
REAR BUMPER CLIPS - SET	1	50.00	30 ✓	50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	20 ✓	30.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	30.00	✓	30.00
REAR TAILGATE NUMBER PLATE	1	25.00	+	25.00
REAR TAILGATE NUMBER PLATE FRAME	1	50.00	+	50.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00	60 ✓	80.00
Subtotal before discount				265.00
Percentage discount 0%				0.00
Sub-total 2				265.00
Parts-total				7,190.28

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	✓	80.00
To remove, reinstall tailgate windscreen	120 ✓	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	60 ✓	80.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	60 ✓	1,000.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MY AUTO LEASING PTE LTD
 397 JOO CHIAT ROAD
 SINGAPORE 427628

Contact : 82687588 89498320

TAX INVOICE

Repair Code : CLM17947
 Date in : 10/06/2024
 Vehicle Num. : SNQ8131Y
 Model : TOYOTA NOAH HYBRID 1.8X CVT
 Chassis/Eng# : ZWR900122112/2ZR2X28635

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	2,470.00
Parts & Labour Total	9,660.28

1580

6W	1,000.00
6W	80.00
6W	80.00

*** This is a computer-generated document which requires no signature.***

page 3

Adm Lj
 L/S 11/06/24.
 06 Rys.

total: 5695.60
 L/S: A.5K ✓

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: