



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555		Ref: CS3/LPC24070278/Rqp3e2 Date: 24/07/2024 Code: LPC2		
1. Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	GBA 843E	Veh. Inspected	FBN 7237R
	Policy No.	-	Coverage	0
	Claim No.	24/24/24/VC05/029538	Excess	\$0.00
	Assign From	GERALD POH	Assign Date	16/07/2024
2. Vehicle Details				
	Make & Model	YAMAHA XABRE TFX150	C.C	150
	Engine No.	G3G8E0037674	Year of Reg.	28/11/2018
	Chassis No.	MH3RG3710JK027969	Colour	MULTI COLOUR
	Odometer	18785 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	FAIR
	Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	110/70-17	MICHELIN	4
	L/H Front Tyre			
	R/H Rear Tyre	140/70-17	MICHELIN	4
	L/H Rear Tyre			
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.				
5. General Information				
	Accident Date	17/06/2024	Inspection Date	17/07/2024 (12:50)
	Survey held at	THONG SHENG MOTORS TRADING BLK 7 PIONEER ROAD NORTH, OFF LOK YANG WAY, #01-50 SINGAPORE 628459.		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.