

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0555/2024/KS
DATE : 16-Jul-24
WIP : 23573

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/07/2024.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Adrian,

3 Days - OK - Allan Boo

28-Aug-24

OWNER'S NAME : MR. SEN SUKANTI
ADDRESS : 5 RHU CROSS
#11-11
SINGAPORE 437434
TELEPHONE : HP +65 91721605
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100441770-08
VEHICLE NO : **SJB 9768 E**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 23/12/2015
ENGINE NO : CZC 504756
CHASSIS NO : WAUZZZ8V5G1050542
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Jul-24
PLACE OF ACCIDENT : BASEMENT CARPARK, COSTA RHEE, SINGAPORE 437434

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJB 9768 E.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER.	S/N \$	360.00	\$ 360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	
4	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,750.00	\$ 500.00
5	TO RESPRAY FRONT BUMPER AND BONNET.	\$	1,800.00	\$ 550.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	\$ 292.00
TOTAL LABOUR CHARGES		: \$	4,552.00	\$ 1,702.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJB 9768 E.

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,670.00	\$	2,136.00
2	FRONT BUMPER FIXING PARTS	1	\$ 209.00		
3	FRONT BUMPER LOWER COVER TRIM - LH / RH	2	\$ 408.00		
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 196.00		
5	FRONT BUMPER PULL STRAP	4	\$ 260.00		
6	FRONT BUMPER GUIDE SECTION - RH	1	\$ 49.00		
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 274.00	\$	109.60
8	RADIATOR GRILLE	1	\$ 850.00	\$	679.60
9	RADIATOR STRIKER PLATE	1	\$ 127.00		
10	FRONT REINFORCEMENT BEAM COVER	1	\$ 71.00		
11	FRONT FOAM FILLER PIECE	1	\$ 172.00		
12	FRONT REINFORCEMENT BEAM	1	\$ 969.00		
13	HEADLIGHT - RH	1	\$ 3,044.00		
14	LIFT CYLINDER - RH	1	\$ 230.00		
15	LIFT CYLINDER HOSE	1	\$ 233.00		
16	RADIATOR AIR GUIDE - LH / RH	2	\$ 78.00		
17	RADIATOR AIR GUIDE SEAL - RH OUTER	1	\$ 10.00		
18	RADIATOR AIR GUIDE - UPPER CENTRE	1	\$ 21.00		
19	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
20	SUNDRIES		\$ 500.00	\$	26.96
TOTAL SPARE PARTS		:	\$ 10,431.00	\$	3,012.16
TOTAL LABOUR CHARGES		:	\$ 4,552.00	\$	1,702.00
GRAND TOTAL		:	\$ 14,983.00	\$	4,714.16

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT