

CS/AIG24070279/Anp3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estin: \_\_\_\_\_  
 OD / TP RES / CD RES / EVA / INV / MV  
 To in Vehicle No: \_\_\_\_\_  
 at W/O \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: **300**  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_  
 (Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repair: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJB 9768E Yr Regn: 2015, Dec.  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or

Make: Audi A3 C.D. 1395

Colour Maroon A/C: Insured / Std / NI / NA

Sp. Reading 62585 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAUZZZ8V5G-1050542

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16  
 R: 205/55R16

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A. \_\_\_\_\_

D.O.I. 19/07/24

Survey held at

Premium

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Rent of

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>OD ALG</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes C</u>
	<u>1st Survey : No C</u>
	<u>MV : 32K</u>
	<u>PV : 19.5K</u>
	<u>Nett : 12.5K</u>
Confirm final fig \$4,714.16 before excess \$300.00 & GST and 3 repair days. (red, \$10268.84, 68%)	

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 3

1)

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

Survey Fee:

2)

Transportation:

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

3 + RS. \$1



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0555/2024/KS  
**DATE** : 16-Jul-24  
**WIP** : 23573

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/07/2024.**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

**OWNER'S NAME** : MR. SEN SUKANTI  
**ADDRESS** : 5 RHU CROSS  
#11-11  
SINGAPORE 437434  
**TELEPHONE** : HP +65 91721605  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** : 2100441770-08  
**VEHICLE NO** : **SJB 9768 E**  
**MODEL CODE** : AUDI A3 SEDAN 1.4 TFSI  
**MODEL YEAR** : 23/12/2015  
**ENGINE NO** : CZC 504756  
**CHASSIS NO** : WAUZZZ8V5G1050542  
**MILEAGE** : KM  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 16-Jul-24  
**PLACE OF ACCIDENT** : BASEMENT CARPARK, COSTA RHEE, SINGAPORE 437434

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJB 9768 E.**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	<del>1,750.00</del> 500	
5	TO RESPRAY FRONT BUMPER AND BONNET.	\$	<del>1,800.00</del> 550	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	✓
<b>TOTAL LABOUR CHARGES</b>		:	<b>\$ 4,552.00</b>	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJB 9768 E.**

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>okhd</i>	1	\$ 2,670.00	✓	
2	FRONT BUMPER FIXING PARTS <i>ren</i>	1	\$ 209.00	+	
3	FRONT BUMPER LOWER COVER TRIM - LH / RH <i>ren</i>	2	\$ 408.00	+	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>ren</i>	1	\$ 196.00	+	
5	FRONT BUMPER PULL STRAP	4	\$ 260.00	+	
6	FRONT BUMPER GUIDE SECTION - RH <i>ren</i>	1	\$ 49.00	+	
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>ren</i>	2	\$ <del>274.00</del> 137.	+	
8	RADIATOR GRILLE <i>at</i>	1	\$ 850.00	✓	
9	RADIATOR STRIKER PLATE <i>ren</i>	1	\$ 127.00	+	
10	FRONT REINFORCEMENT BEAM COVER <i>ren</i>	1	\$ 71.00	+	
11	FRONT FOAM FILLER PIECE <i>ren</i>	1	\$ 172.00	+	
12	FRONT REINFORCEMENT BEAM <i>ren</i>	1	\$ 969.00	+	
13	HEADLIGHT - RH <i>ren</i>	1	\$ 3,044.00	+	
14	LIFT CYLINDER - RH <i>ren</i>	1	\$ 230.00	+	
15	LIFT CYLINDER HOSE <i>ren</i>	1	\$ 233.00	+	
16	RADIATOR AIR GUIDE - LH / RH <i>ren</i>	2	\$ 78.00	+	
17	RADIATOR AIR GUIDE SEAL - RH OUTER <i>ren</i>	1	\$ 10.00	+	
18	RADIATOR AIR GUIDE - UPPER CENTRE <i>ren</i>	1	\$ 21.00	+	
19	FRONT NO PLATE <i>Defrd</i>	S/N	\$ 60.00	✓	
20	SUNDRIES <i>?</i>		\$ 500.00	?	
<b>TOTAL SPARE PARTS</b>			<b>\$ 10,431.00</b>		
<b>TOTAL LABOUR CHARGES</b>			<b>\$ 4,552.00</b>		
<b>GRAND TOTAL</b>			<b>\$ 14,983.00</b>		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Adrian L  
19/07/24.

Not Authorized, 03 Days.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT