

ASSIGNMENT

From: _____ Date: _____

Estimate: _____

OD / TP RES / OD RES / EVA / INV / MV

To In _____ Vehicle No: _____

at _____

of _____

Insured: _____

Policy No: _____

Claim No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remarks: The vehicle had commenced its repair at the time of inspection.

Ball. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJB9768E Yr Regn: 2015, Dec.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 C.C. 1395

Colour: Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 62585 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZ28V5G1050542

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16
R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 19/07/24

Survey held at Premium

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

00 ALG

COE Expiry: _____

Estimate given during: Yes C /
1st Survey: No C /

MV: 32K

PV: 19.5K

Nett: 12.5K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Survey Fee:

Transportation:

3 + R8 \$

Photos

Others

Report Format:

Report Format: _____

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0555/2024/KS
DATE : 16-Jul-24
WIP : 23573

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/07/2024.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR. SEN SUKANTI
ADDRESS : 5 RHU CROSS
#11-11
SINGAPORE 437434
TELEPHONE : HP +65 91721605
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100441770-08
VEHICLE NO : **SJB 9768 E**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 23/12/2015
ENGINE NO : CZC 504756
CHASSIS NO : WAUZZZ8V5G1050542
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Jul-24
PLACE OF ACCIDENT : BASEMENT CARPARK, COSTA RHEE, SINGAPORE 437434

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJB 9768 E.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER.	S/N \$	360.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	X
4	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,750.00 500	
5	TO RESPRAY FRONT BUMPER AND BONNET.	\$	1,800.00 550	
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	✓
TOTAL LABOUR CHARGES		:	\$ 4,552.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJB 9768 E.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>okhd</i>	1	\$ 2,670.00	✓
2	FRONT BUMPER FIXING PARTS <i>ren</i>	1	\$ 209.00	+
3	FRONT BUMPER LOWER COVER TRIM - LH / RH <i>ren</i>	2	\$ 408.00	+
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>ren</i>	1	\$ 196.00	+
5	FRONT BUMPER PULL STRAP	4	\$ 260.00	+
6	FRONT BUMPER GUIDE SECTION - RH <i>gas</i>	1	\$ 49.00	+
7	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>ren</i>	2	\$ 274.00 137.	+
8	RADIATOR GRILLE <i>at</i>	1	\$ 850.00	✓
9	RADIATOR STRIKER PLATE <i>ren</i>	1	\$ 127.00	+
10	FRONT REINFORCEMENT BEAM COVER <i>ren</i>	1	\$ 71.00	+
11	FRONT FOAM FILLER PIECE <i>ren</i>	1	\$ 172.00	+
12	FRONT REINFORCEMENT BEAM <i>ren</i>	1	\$ 969.00	+
13	HEADLIGHT - RH <i>gas</i>	1	\$ 3,044.00	+
14	LIFT CYLINDER - RH <i>ren</i>	1	\$ 230.00	+
15	LIFT CYLINDER HOSE	1	\$ 233.00	+
16	RADIATOR AIR GUIDE - LH / RH <i>ren</i>	2	\$ 78.00	+
17	RADIATOR AIR GUIDE SEAL - RH OUTER <i>ren</i>	1	\$ 10.00	+
18	RADIATOR AIR GUIDE - UPPER CENTRE <i>ren</i>	1	\$ 21.00	+
19	FRONT NO PLATE <i>Deford</i>	S/N	\$ 60.00	✓
20	SUNDRIES <i>?</i>		\$ 500.00	?
TOTAL SPARE PARTS			\$ 10,431.00	
TOTAL LABOUR CHARGES			\$ 4,552.00	
GRAND TOTAL			\$ 14,983.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adnan Lj

SURVEYED DATE

:

19/07/24.

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorized, 03 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.

FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: