



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: -

Date: 13th Aug 2024

Our Ref: CD/MIDA24070284/Dpp

M/s Ministry Of Dedence

HQ Transport Command
Kranji Camp 3
151 Choa Chu Kang
Singapore 688248
(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBF 3101S
INSURED VEHICLE: MID 34467
ACCIDENT DATE: 08/09/2018

We thank you for your instruction on 18/07/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GBF 3101S from M/s Indeco Engineers Pte Ltd.
- b) Colour damaged vehicle photographs of GBF 3101S.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GBF3101S
Make & Model	: HYUNDAI H1 STAREX 2.5 CRDI AT 5DR
Chassis Number	: KMFWBX7KMGU818866
Year of Registration	: 09 SEP 2016
Engine Capacity	: 2497cc



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

2. Our finding is that the repair cost of \$988.80 (before GST) quoted by M/s Indeco Engineers Pte Ltd is fair & reasonable.

3. We recommend that the repairs of the entire damage require about 2 (Two) working days to complete.

Your Faithfully,

ANG BRYAN TANI
Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.

19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBF 3101S

Labour			
	Description of Parts	Condition	Our Adjusted (\$)
	TO REPAIR AND RESPRAY REAR BUMPER		\$370.80
	TO REPAIR AND RESPRAY RH TAILLAMP LOWER GARNISH		\$123.60
	TO REPAIR AND RESPRAY RHR BODY PANEL		\$494.40
			\$988.80
GRAND TOTAL			\$988.80
RECOMMENDED COST OF REPAIRS			\$988.80
Report Ref No: CD/MIDA24070284/Dpp			

ABT

ANG BRYAN TANI

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.