



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Not Authorized
Mr
moray

24 July 2024

REG NO.: GBJ 5599 E
MAKE/MODEL: NISSAN NV200

2/5 \$14,600
12 days

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>NETT ITEMS</u>		
1	Front bonnet <i>BUC</i>	\$ 858.60 ✓
2	Front bonnet hinges <i>Bent</i>	\$ 90.40 ✓
1	Front bonnet lock <i>Bent</i>	\$ 67.90 ✓
1	Front bonnet insulator <i>NF</i>	\$ 124.50 X
2	Front headlamps <i>holder one 620.50 x 2 = 1241</i>	\$ 1,730.00 ✓
2	Front headlamp top panels <i>Bent/BUC</i>	\$ 230.40 ✓
2	Front headlamp side panels <i>Bent</i>	\$ 270.00 ✓
2	Front headlamp lower garnishes <i>Torn</i>	\$ 697.20 ✓
1	Front grille <i>CNG</i>	\$ 507.10 ✓
1	Front grille logo <i>SUR</i>	\$ 75.20 ✓
1	Front bumper <i>DIS 683.20</i>	\$ 892.00 ✓
1	Front bumper inner sponge <i>NF</i>	\$ 280.70 X
1	Front bumper reinforcement <i>Bent 512.20</i>	\$ 591.90 ✓
2	Front bumper side retainers <i>CNG</i>	\$ 80.40 ✓
1	Front bumper tow hook cover <i>Torn</i>	\$ 19.40 ✓
2	Front fenders <i>N/S R o/s BUC 548.80</i>	\$ 1,097.60 <i>1 PC</i>
2	Front fender inner shields <i>11</i>	\$ 154.20 X
1	Front support panel <i>Bent</i>	\$ 325.30 ✓
1	Front support panel top garnish <i>11</i>	\$ 76.80 X
1	Front lower cross member <i>11</i>	\$ 325.00 X
2	Horns <i>11</i>	\$ 176.20 X
1	Air con condenser <i>Bent/Pun</i>	\$ 767.80 ✓
1	Oil cooler <i>11</i>	\$ 1,657.30 X
1	Oil cooler air duct <i>Torn</i>	\$ 123.00 ✓
1	Radiator <i>Bent/Pun 788.20</i>	\$ 985.20 ✓
1	Radiator side garnishes <i>Torn</i>	\$ 196.00 ✓
1	Radiator fan assy <i>DD</i>	\$ 572.60 ✓
1	Radiator spare tank <i>DE</i>	\$ 81.50 ✓
1	Radiator top hose <i>11</i>	\$ 80.00 X
1	Air intake duct <i>Reptd</i>	\$ 179.00 X
1	Front wiper tank <i>DE</i>	\$ 242.40 ✓
1	Rear windscreen inner seal <i>VS</i>	\$ 85.00 X
1	Rear tailgate <i>Body 2031.20</i>	\$ 2,201.40 ✓
2	Rear tailgate dampers <i>11</i>	\$ 360.00 X
1	Rear tailgate inner board <i>Torn</i>	\$ 355.00 ✓
1	Rear tailgate inner lock <i>Daye 260.60</i>	\$ 360.10 ✓
1	Rear tailgate logo <i>11</i>	\$ 188.30 X
1	Rear tailgate outer garnish <i>11</i>	\$ 370.90 X
1	Rear tailgate rubber <i>Torn</i>	\$ 200.80 ✓
1	Rear tailgate "70KM/H" sticker <i>11</i>	\$ 28.00 <i>10 S/W</i>
1	Rear tailgate "6PAX" sticker <i>11</i>	\$ 28.00 <i>10 S/W</i>
		\$ 17,733.10

c/f: \$

17,733.10

NETT ITEMS

1	Rear tailgate "NV200" emblem	den	\$ 115.00	163.50
2	Rear taillamps	N/S 110/500	\$ 284.80	569.60 1PC
1	Rear end panel	body 20	\$ 411.20	642.70
1	Rear end panel inner member	body 20	\$	588.50
1	Rear end panel inner garnish	701	\$	125.00
1	Rear bumper	D.S	\$	624.80
1	Rear bumper inner sponge	To. 1	\$	133.80
2	Rear bumper side retainers	N/S 110/500	\$ 65.00	200.60 1PC
1	Rear bumper tow hook cover	cup	\$ 25.00	48.00
1	Rear floor panel	crushed	\$	1,586.40
1	Rear spare tyre carriage		\$	244.70 X
1	Rear spare tyre lock catch	11	\$	178.50 X
1	Rear side panel -RH	11	\$	2,435.80 X
			\$	25,275.00
			Less 10%	\$ 2,527.50
				\$ 22,747.50

SPECIAL NETT ITEMS

1	Front bonnet insulator clip (1 set)	11	\$	45.00 X
1	Front grille clip (1 set)	11	\$	25.00 X
1	Front bumper clip (1 set)	11	\$	50.00 30
1	Front number plate with holder	buf	\$	50.00 40
2	Front fender inner shield clips (2 set)	11	\$	70.00 X
1	Rear windscreen sealant	11	\$	80.00 40
1	Rear tailgate advertisement sticker	11	\$	300.00 X
1	Rear bumper clip (1 set)	11	\$	60.00 30
1	Rear number plate with holder	11	\$	50.00 X
1	Rear reverse sensor (1 set)	one	\$	350.00 200
1	Rear reverse camera	11	\$	450.00 X
			\$	1,530.00

S/N**LABOUR CHARGES**

1	To check wiring and reset headlamps focusing.	\$	80.00 20
2	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00 20
3	To remove and refit inner garnishes.	\$	150.00 X
4	To remove and refit rear reverse sensor and camera.	\$	150.00 30
5	To transfer rear tailgate mechanism and wiring assembly.	\$	80.00 60
6	To remove, replace air-con condenser, refill gas & conduct leakage test.	\$	180.00 100
7	To remove and refit rear windscreen glass.	\$	180.00 100
8	To apply undercoating.	\$	250.00 80
9	Panel beating.	\$	2,400.00 1800
10	To re-spray painting on the affected areas.	\$	2,200.00 1600
		\$	5,750.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 2 of 2

Acknowledged by Repairer

Signature:

Date:

\$ 26,477.50

2-1578570
102
1427.13
340
3810
18387.13
14685