



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

email | zoomautowerks@gmail.com

Not Authorized

D.O.A : 7TH JUNE 2024

10th June 2024

OWNER : CHEN YONG

REG. NO. : SJY 6436 L

MAKE/MODEL : TOYOTA ALTIS

10/6/24
1/5 @ 1600 /
3 days
Take photo After repair

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMOUNT(S\$)
<u>LIST ITEMS</u>		
1	Front Headlamp - LH holder cne	\$ 820.10 930.50 /
1	Front Grille ^ ^	\$ 312.80 X
1	Front Grille Logo ^ ^	\$ 68.55 X
1	Front Grille Chrome Moulding Lower ^ ^	\$ 68.75 X
1	Front Grille Chrome Moulding Top ^ ^	\$ 48.26 X
1	Front Bumper cny / Bm	\$ 552.90 /
1	Front Bumper Centre Grille ^ ^	\$ 101.80 X
1	Front Bumper Fog Lamp cne	\$ 280.70 /
1	Front Bumper Fog Lamp Cover cne	\$ 56.07 /
1	Front Bumper Reinforcement ^ ^	\$ 399.66 X
2	Front Bumper Side Retainers su	\$ 99.68 X
		\$ 2,919.67
LESS 25%		\$ 729.92
		\$ 2,189.75

SPECIAL NETT ITEMS

1	Front Bumper Clip (1 Set) nca	\$ 35.00 30
		\$ 35.00

S/N LABOUR CHARGES

1	To check wiring and reset headlamps focusing.	\$ 80.00 20
2	To apply undercoating	\$ 100.00 X
3	Panel Beating	\$ 1,200.00 280
4	To re-spray the affected areas	\$ 1,000.00 400
		\$ 2,380.00

TOTAL @ 4604.75

2- 1709.77
252
1281.33
30
700
2012.37

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: