

VAG Singapore Pte Ltd
48 Toh Guan Road East
#05-136, Enterprise Hub
Singapore 608586

Tel: 6267 9916
Fax: 6267 9313
www.avantage.sg

Date : 17-Jul-2024

Vehicle Num : SMA9010C

Make/Model : TOYOTA / HARRIER PREMIUM 2.0

Chassis No : ZSU600081234

S/N	PARTS	QTY	PRICE	TOTAL
1	Front door Rh / nn	1	\$ 1,195.26	\$ 1,195.26
2	Front door handle Rh	1	\$ 247.95	\$ 247.95
3	Front door chrome molding Rh - GR	1	\$ 128.25	\$ 128.25
4	Front door window chrome molding Rh / BT	1	\$ 119.78	\$ 119.78
5	Front door weathership Rh / DEF	1	\$ 168.32	\$ 168.32
6	Front door hinge	2	\$ 68.47	\$ 136.94
7	Front door lock Rh ?	1	\$ 342.54	\$ 342.54
8	Front window lifter rh	1	\$ 166.45	\$ 166.45
9	Rocket panel Rh / CUT	1	\$ 487.35	\$ 487.35
10	Side mirror assembly Rh X nn	1	\$ 513.30	\$ 513.30
	Total Parts			\$ 3,506.14
	Less 25%			\$ 876.54
	TOTAL AMOUNT			\$ 2,629.61
	MISCELLANEOUS ITEM			
1	Sundries		\$ MC 37.50	\$ 20 37.50
	LABOUR			
1	To remove and refitting front door Rh, side mirror assembly Rh and rocket panel beating and each other.		\$ 960.00	\$ 250 960.00
2	Surface preparation, spray paint and polish front door Rh, rocket panel Rh and other affected areas.		\$ 750.00	\$ 250 750.00
3	To perform diagnosis check		\$ 80.00	\$ 30 80.00
	TOTAL		\$ 1,790.00	\$ 4,457.11
	GST 9%			\$ 401.14
	GRAND TOTAL			\$ 4,858.24

LKK Auto Consultants hence notify
the Repairer of the following:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: