

DICKSON AUTO CARE CENTRE PTE LTD 29 UBI ROAD 4, DICKSON AUTO CENTRE SINGAPORE 408619

TEL: 6668 1122 | FAX: 6668 1123

19/7/24, 13.00 L/S

QUOTATION

DATE: 16/07/2024

REF: SMV6229Z_130724

VEHICLE NO.: SMV6229Z MAKE: VOLVO

MODEL: S90
PREPARED BY: POON

QUOTATION FOR

NAME: MS First Capital Insurance Ltd

COMPANY NAME: MS First Capital Insurance Ltd STREET ADDRESS: 6 Raffles Quay, #21-00 POSTAL CODE: Singapore 048580

PHONE: 6222 2311

S/N	DESCRIPTION	QTY	иом	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
	LABOUR						
1	REMOVE & REFIT HEADLAMP ASSY & SENSOR	3		\$400.00	\$ 1,200.00	250	\$ 1,200.00
2	SPRAY PAINT FROT RH FENDER, FRONT BUMPER & LOWER SPOILER	3		\$300.00	\$ 900.00	500	\$ 900.00
3	CHECK & TEST FOR PROPER FUNCTIONING FOR HEADLAMP & FRONT SENSOR	1		\$80.00	\$ 80.00	/	\$ 80.00
	PARTS						
1	FRONT BUMPER X	1		\$2,300.00	\$ 2,300.00		\$ 2,300.00
2	FRONT BUMPER LOWER SPOILER X	1 1		\$680.00	\$ 680.00		\$ 680.00
3	FRONT RIGHT HEADLAMP ASSY	MA DOP CUT		\$3,850.00	\$ 3,850.00		\$ 3,850.00
4	FRONT BUMPER SENSOR (RH)	1		\$130.00	\$ 130.00		\$ 130.00
				SUBTOTAL	\$ 9,140.00	SUBTOTAL	\$ 9,140.00
ARKS:				GST 9%	\$ 822,60	GST 9%	\$ 822.60
A				TOTAL	\$ 9,962.60	TOTAL	\$ 9,962.60

LAGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD



(CUSTOMER'S SIGNATURE AND COMPANY STAMP)

(AUTHORISED SIGNATURE)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

