



DICKSON GROUP

Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

Steve (LKK)
19/7/24, 12.00pm

LK

L/S

LK

3 d/s

QUOTATION

DATE: 16/07/2024

REF: SMV6229Z_130724

VEHICLE NO.: SMV6229Z

MAKE: VOLVO

MODEL: S90

PREPARED BY: POON

QUOTATION FOR

NAME: MS First Capital Insurance Ltd

COMPANY NAME: MS First Capital Insurance Ltd

STREET ADDRESS: 6 Raffles Quay, #21-00

POSTAL CODE: Singapore 048580

PHONE: 6222 2311

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
LABOUR							
1	REMOVE & REFIT HEADLAMP ASSY & SENSOR	3		\$400.00	\$ 1,200.00	250	\$ 1,200.00
2	SPRAY PAINT FROT RH FENDER, FRONT BUMPER & LOWER SPOILER	3		\$300.00	\$ 900.00	500	\$ 900.00
3	CHECK & TEST FOR PROPER FUNCTIONING FOR HEADLAMP & FRONT SENSOR	1		\$80.00	\$ 80.00	/	\$ 80.00
PARTS							
1	FRONT BUMPER X R	1		\$2,300.00	\$ 2,300.00		\$ 2,300.00
2	FRONT BUMPER LOWER SPOILER X R	1		\$680.00	\$ 680.00		\$ 680.00
3	FRONT RIGHT HEADLAMP ASSY / dip cut	1		\$3,850.00	\$ 3,850.00		\$ 3,850.00
4	FRONT BUMPER SENSOR (RH) X nn	1		\$130.00	\$ 130.00		\$ 130.00
3850.00					SUBTOTAL	\$ 9,140.00	SUBTOTAL \$ 9,140.00
-10%					GST 9%	\$ 822.60	GST 9% \$ 822.60
3465					TOTAL	\$ 9,962.60	TOTAL \$ 9,962.60

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

4295

L/S - 3436
= 3450



(CUSTOMER'S SIGNATURE AND COMPANY STAMP)

(AUTHORISED SIGNATURE)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: