

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2400655

INV Date : 19-09-2024

Reference CD/FCI24070292/Tma3

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMN 355Z
Insured Veh. SHC 2885P
Claim No. D24006202MFCT/CTPL/TPD2/KT
Policy No. D-24101861MFCT
Accident Date 14/07/2024
Inspection Date 17/07/2024

Description	Amount
Third Party Express Settlement	350.00
Sub-Total	350.00
GST (9%)	31.50
Grand Total	381.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CD/FCI24070292/Tma3
16 RAFFLES QUAY	Date:	19/09/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SHC 2885P	Veh. Inspected	SMN 355Z
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24006202MFCT/CTPL/TPD2/KT	Excess	\$0.00
Assign From	KAREN TAN	Assign Date	16/07/2024

2. Vehicle Details

Make & Model	RENAULT GRAND SCENIC IV 1.5 DCI AT EU6	C.C	1461
Engine No.	K9KF649D059912	Year of Reg.	23/07/2019
Chassis No.	VF1RFA00262895255	Colour	BLACK
Odometer	311903 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/55 R20	DAVANTI	6
L/H Front Tyre	195/55 R20	DAVANTI	6
R/H Rear Tyre	195/55 R20	DAVANTI	6
L/H Rear Tyre	195/55 R20	DAVANTI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/07/2024	Inspection Date	17/07/2024
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMN 355Z

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT DOOR RH	BENT	\$2,199.03	\$1,650.00
1	PROTECTOR FRT RH DOOR	CUT	\$673.90	\$530.00
1	DOOR LOCK MECH FRTRH	NOT NECESSARY	\$447.81	\$0.00
1	WINDOW MOULDING FRT RH	NOT NECESSARY	\$434.93	\$0.00
1	DOOR HINGE RH FRT & RR (UPPER)	NOT NECESSARY	\$246.90	\$0.00
1	DOOR HINGE LH/RH ,FRT & RR (LOWER)	NOT NECESSARY	\$246.90	\$0.00
1	DOOR CHECK FRT LH & RH	NOT NECESSARY	\$124.31	\$0.00
1	WINDOW REGULATOR FRT RH	NOT NECESSARY	\$688.62	\$0.00
1	REAR DOOR REAR RH	TO REPAIR SEE LABOUR	\$2,209.38	\$0.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$218.00)
			\$7,271.78	\$1,962.00

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
7	FRONT DOOR CLIP SET RH (SN)	NECESSARY	\$49.00	\$49.00
7	REAR DOOR CLIP SET RH (SN)	NOT NECESSARY	\$49.00	\$0.00
			\$98.00	\$49.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR FOR SPRAY PAINT FRONT DOOR RH ,REAR DOOR RH AND ALL AFFECTED AREAS	NOT NECESSARY	\$600.00	\$600.00
	TO APPLY ANTI RUST		\$150.00	\$30.00
	ELECTRICAL WORK		\$45.00	\$0.00
	TO TRANSFER FRONT DOOR RH & MECHANISM RH		\$180.00	\$60.00
	LABOUR FOR PANEL BEATING AND REPLACE FRONT DOOR RH ,REAR DOOR RH AND ALL AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF REAR DOOR REAR RH .		\$800.00	\$500.00
			\$1,775.00	\$1,190.00

GRAND TOTAL			\$9,144.78	\$3,201.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$2,550.00

Report Ref No: CD/FCI24070292/Tma3



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R


MTH

MOHAMAD TAUFIKH

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SMN 355Z



PHOTOGRAPHS FOR VEHICLE NO. : SMN 355Z





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 8)

PHOTOGRAPHS FOR VEHICLE NO. : SMN 355Z





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 8)

PHOTOGRAPHS FOR VEHICLE NO. : SMN 355Z





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 5 of 8)


PHOTOGRAPHS FOR VEHICLE NO. : SMN 355Z



PHOTOGRAPHS FOR VEHICLE NO. : SMN 355Z



PHOTOGRAPHS FOR VEHICLE NO. : SMN 355Z



PHOTOGRAPHS FOR VEHICLE NO. : SMN 355Z





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SMN 355Z



PHOTOGRAPHS FOR VEHICLE NO. : SMN 355Z

