

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile MS STRIDES PREMIER AUTOMOTIVE SERVICES PL. Ref: CS3/SMR24070294/Evp3e2 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE Date: 01/08/2024 757705 Code: SMR 1. **Policy Particulars :- PRE-REPAIR SURVEY** Insured Veh. **SHB 821S** Veh. Inspected **FBR 7370S** Policy No. Coverage 0 Claim No. TAX/07/24/2028 **Excess** \$0.00 **Assign From HUA YEN** Assign Date 18/07/2024 2. **Vehicle Details** C.C Make & Model 149 HONDA WINNER X Engine No. KC34E1131428 Year of Reg. 03/10/2020 Chassis No. RLHKC3717LY801823 Colour **GREY** Odometer **IN ORDER** - KM Steering **Brakes** IN ORDER GOOD General Modification(s) RIMS: SPORTS RIM **Conditions of Tyres** 3. Size Make Balance (mm) 90/80-17 **PIRELLI R/H Front Tyre** 5 L/H Front Tyre R/H Rear Tyre 120/70-17 **PIRELLI** 5 L/H Rear Tyre **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY. 5. **General Information Accident Date** 09/07/2024 **Inspection Date** 18/07/2024 (13:42) Survey held at GLEN ENTERPRISE PTE LTD 1100/1102 SERANGOON ROAD SINGAPORE 328196 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$2,500 5b **Estimate Days of Repair**

CTY

CHEN TSUE YEE

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days