

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE SINGAPORE 757705

INV No. : SAC2400180

INV Date : 01-08-2024

Reference CS3/SMR24070294/Evp3e2

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. FBR 7370S

Insured Veh. SHB 821S

Claim No. TAX/07/24/2028

Policy No.

Accident Date 09/07/2024

Inspection Date 18/07/2024

Description	Amount
Pre-Repair Survey	128.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS STRIDES PREMIER AUTOMOTIVE SERVICES PL.	Ref:	CS3/SMR24070294/Evp3e2
60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Date:	01/08/2024
	Code:	SMR

1. Policy Particulars :- PRE-REPAIR SURVEY

Insured Veh.	SHB 821S	Veh. Inspected	FBR 7370S
Policy No.	-	Coverage	0
Claim No.	TAX/07/24/2028	Excess	\$0.00
Assign From	HUA YEN	Assign Date	18/07/2024

2. Vehicle Details

Make & Model	HONDA WINNER X	C.C	149
Engine No.	KC34E1131428	Year of Reg.	03/10/2020
Chassis No.	RLHKC3717LY801823	Colour	GREY
Odometer	- KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	90/80-17	PIRELLI	5
L/H Front Tyre			
R/H Rear Tyre	120/70-17	PIRELLI	5
L/H Rear Tyre			

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.

5. General Information

Accident Date	09/07/2024	Inspection Date	18/07/2024 (13:42)
Survey held at	GLEN ENTERPRISE PTE LTD 1100/1102 SERANGOON ROAD SINGAPORE 328196		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$2,500

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days

CTY

CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.


PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S




PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S




PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S





PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S



PHOTOGRAPHS FOR VEHICLE NO. : FBR 7370S

