

ASS. REG. BY:

REF:

U/S MR 24070295/Kap3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____ Yesof _____ 1150

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$ 65k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

2/1 11Pm \$4050r Colour (Red & 10397.10, 772)

Date/Time, File Pass to?

1) 06/11/2024

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.L. (\$) TP
4050☐ : Prel. Report☐ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation

S - RS - SI

F - Photos

Others

TOTAL

Veh No: SL 8 34657 Yr Regn: 04, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A) WagonMake: Subaru Forester C.G. 1995Colour: White A/C: Insured / Std / NI / NASp. Reading: 97996 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JFISJ5KC5JG108235

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Competus

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 5 mmL/Bal. 7 mm L/Bal. 3 mmD.O.A. 15/7/24 D.O.I. 18/7/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopteltd@gmail.com
Registration No: 201719251W GST No: 201719251W

M/S : First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 15/07/2024
TP Veh Reg No: SHB1338P

Not Authorized
11 Pp @ 4050h
Running After Paim
4 days

Estimate No: ES2400074
Date: 16 Jul 2024
Policy No:
Veh Reg No: SLZ3465T
Make/Model: SUBARU FORESTER
2.0I-L CVT AWD SR
Chassis No: JF1SJ5KC5JG108235
Engine No: FB20YD45015
Reg. Date: 28/04/2018

Estimate Repair Cost to Vehicle No :SLZ3465T

Description	U/Price	Quantity	List Price SS	Amount SS
Net Price				
1 REAR TYRE	400.00	1 PC	<i>in</i> 400.00 <i>X</i>	
2 REAR WHEEL RIM	1,250.00	1 PC	<i>on</i> 1,250.00 <i>850</i>	1,650.00
			1,650.00	1,650.00
Spare Parts				
3 REAR BUMPER <i>794</i>	995.20	1 PC	<i>cm</i> 995.20 <i>✓</i>	
4 REAR BUMPER CLIPS	100.00	1 SET	<i>na</i> 100.00 <i>500</i>	
5 REAR BUMPER SIDE RETAINER - LH	75.00	1 PC	<i>cm</i> 75.00 <i>✓</i>	
6 REAR BUMPER SIDE RETAINER - RH	75.00	1 PC	<i>na</i> 75.00 <i>X</i>	
7 REAR DOOR - LH	1,220.00	1 PC	<i>na</i> 1,220.00 <i>X</i>	
8 REAR DOOR GLASS OUTER MOULDING - LH	195.00	1 PC	<i>na</i> 195.00 <i>X</i>	
9 REAR KNUCKLE ARM - LH <i>905.80</i>	1,105.80	1 PC	<i>na</i> 1,105.80 <i>✓</i>	
10 REAR LOWER ARM - LH	555.10	1 PC	<i>dis</i> 555.10 <i>✓</i>	
11 REAR FENDER - LH	1,755.50	1 PC	<i>na</i> 1,755.50 <i>X</i>	
12 REAR WHEEL BEARING - LH	425.10	1 PC	<i>na</i> 425.10 <i>✓</i>	
13 REAR SHOCK ABSORBER - LH <i>1052.60</i>	1,650.20	1 PC	<i>na</i> 1,650.20 <i>X</i>	
14 REAR FENDER INNER SHIELD - LH	185.20	1 PC	<i>cm</i> 185.20 <i>✓</i>	
15 REAR FENDER INNER SHIELD CLIP <i>205</i>	80.00	1 SET	<i>na</i> 80.00 <i>✓</i>	
			8,417.10	8,417.10
Labour				
16 TO DISMANTLE & REPLACE DAMAGED PARTS. PANEL BEAT WHERE NECESSARY.	1,800.00	1 JOB	1,800.00 <i>500</i>	
17 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,800.00	1 JOB	1,800.00 <i>440</i>	
18 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	<i>na</i> 200.00 <i>X</i>	
19 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00 <i>20</i>	
20 TO REMOVE/RENEW REAR UNDERCARRIAGE	350.00	1 PC	350.00 <i>100</i>	
21 WHEEL ALIGNMENT	150.00	1 T	150.00 <i>60</i>	
			4,380.00	4,380.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No: 201719251W GST No: 201719251W

M/S : First Capital Insurance Ltd
36 Robinson Road
#16-01 City House
Singapore 068877

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 15/07/2024
TP Veh Reg No: SHB1338P

Estimate No: ES2400074
Date: 16 Jul 2024
Policy No:
Veh Reg No: SLZ3465T
Make/Model: SUBARU FORESTER
2.0I-L CVT AWD SR
Chassis No: JF1SJ5KC5JG108235
Engine No: FB20YD45015
Reg. Date: 28/04/2018

Estimate Repair Cost to Vehicle No :SLZ3465T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
			Total	S\$ 14,447.10
			Add GST @ 9%	1,300.24
			Total Amount Payable	S\$ 15,747.34

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND SEVEN HUNDRED FORTY SEVEN AND CENTS THIRTY FOUR ONLY

For Yee Auto Pte Ltd


AUTHORISED SIGNATURE

R039587
18.7.24 13:45
SLZ3465T
160-0217



Subaru : Forester : 2016-18 (SJ)
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
0°10'	0°10'	-0°45' 0°45'
5°40'	5°40'	4°55' 6°25'
-0°05'	-0°05'	-0°05' 0°05'
14°34'	14°34'	
14°44'	14°44'	

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
0°12'	0°12'	-0°45' 0°45'
5°32'	5°32'	4°55' 6°25'
0°16'	0°16'	-0°05' 0°05'
14°48'	14°48'	
15°00'	15°00'	

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°02'	-0°02'	-0°35' 0°35'
0°08'	0°08'	
-0°14'	-0°14'	
0°11'	0°11'	-0°15' 0°15'

Rear : Left

Actual	Before	Specified Range
-2°25'	-2°26'	-1°50' -0°20'
-1°29'	-1°30'	-0°05' 0°05'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°02'	-1°02'	-1°50' -0°20'
0°15'	0°15'	-0°05' 0°05'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	Before	Specified Range
-1°23'	-1°23'	-0°45' 0°45'
-1°14'	-1°14'	-0°15' 0°15'
-0°52'	-0°52'	-0°30' 0°30'