

Date: 19-7-2024
Vehicle No: GBD8572T
Model: Nissan NV350
Chassis: JN1MC2E26Z0004313
Reg.Year: 10.6.2015

Not Authorized
7/10/24

Third Party Insurer: China Taiping
Third Party Veh No: CB356C
Date of Accident: 9/7/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		<i>2</i> \$2,500.00
2	FRONT BUMPER TOWING COVER	1		<i>mi</i> \$120.00
3	FRONT LH BUMPER FOG LAMP COVER	1		<i>mi</i> \$180.00
4	FRONT RH BUMPER FOG LAMP COVER	1		<i>mi</i> \$180.00
5	FRONT BUMPER REINFORCEMENT	1		<i>B</i> \$1,500.00
6	FRONT BUMPER BAR	1		<i>nsp</i> \$1,000.00
7	FRONT LH BUMPER STAY	1		<i>mi</i> \$750.00
8	FRONT RH BUMPER STAY	1		<i>mi</i> \$750.00
9	FRONT LH BUMPER SIDE BRACKET	1		<i>cm</i> \$260.00
10	FRONT RH BUMPER SIDE BRACKET	1		<i>cm</i> \$260.00
11	FRONT PANEL CENTER	1		<i>B</i> \$5,000.00
12	FRONT PANEL INSULATOR	1		<i>m</i> \$250.00
13	FRONT PANEL LOWER LH	1		\$4,300.00
14	FRONT PANEL LOWER RH	1		\$4,300.00
15	FRONT LH CORNER PANEL	1		<i>B</i> \$1,500.00
16	FRONT RH CORNER PANEL	1		<i>B</i> \$1,500.00
17	FRONT WINDSCREEN	1		<i>cm</i> \$1,680.00
18	DASHBOARD	1		<i>cm</i> \$4,500.00
19	STEERING AIRBAG	1		<i>Bm</i> \$1,260.00
20	AIRBAG CONTROL MODULE	1		<i>m</i> \$2,800.00
21	FRONT LH AIRBAG SENSOR	1		<i>m</i> \$530.00
22	FRONT RH AIRBAG SENSOR	1		<i>m</i> \$530.00
23	RADIATOR GRILLE	1		<i>mi</i> \$1,180.00
24	RADIATOR GRILLE EMBLEM	1		<i>mi</i> \$350.00
25	INTERCOOLER	1		<i>B</i> \$1,950.00
26	FRONT RH DOOR PANEL	1		<i>B</i> \$4,500.00
27	FRONT RH DOOR INNER TRIM BOARD	1		<i>cm</i> \$3,900.00
28	FRONT RH DOOR POWER WINDOW REGULATOR	1		<i>B</i> \$2,530.00
29	FRONT RH DOOR POWER WINDOW REGULATOR MOTOR	1		<i>Im</i> \$1,600.00
30	FRONT WINDSCREEN MOULDING	1		<i>m</i> \$180.00
31	FRONT LH SEAT BELT	1		<i>Im</i> \$1,450.00
32	FRONT RH SEAT BELT	1		<i>Im</i> \$1,450.00
33	A/C DISCHARGE HOSE	1		<i>pd</i> \$1,670.00
34	A/C SUCTION HOSE	1		<i>pd</i> \$1,780.00
35	A/C LIQUID HOSE	1		<i>m</i> \$1,550.00
36	FRONT RH DOOR GLASS	1		<i>Bu</i> \$1,490.00
37	FRONT LH DOOR PANEL	1		<i>B</i> \$4,500.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 19-7-2024
 Vehicle No: GBD8572T
 Model: Nissan NV350
 Chassis: JN1MC2E26Z0004313
 Reg.Year: 10.6.2015

Third Party Insurer: China Taiping
 Third Party Veh No: CB356C
 Date of Accident: 9/7/2024
 Estimator: Loong
 Surveyor:

38	FRONT LH DOOR INNER TRIM BOARD	1	CM	\$3,900.00	✓
39	FRONT LH SIDE MIRROR	1	Bo	\$1,785.00	✓
40	FRONT LH DOOR GLASS	1	Thot	\$1,490.00	✓
41	FRONT LH DOOR WEATHERSTRIP	1	Gr	\$570.00	50lin
42	FRONT RH SIDE MIRROR	1	mi	\$1,785.00	✓
43	REAR RH DOOR PANEL	1	R	\$4,500.00	X
44	REAR RH FENDER PANEL	1	R	\$5,580.00	X
45	FRONT RH DOOR WEATHERSTRIP	1	Tn	\$570.00	50lin
46	FRONT LH WIPER ARM	1	R	\$350.00	X
47	FRONT RH WIPER ARM	1	R	\$350.00	✓
48	FRONT LH OUTER DOOR HANDLE	1	R	\$380.00	✓
49	FRONT LH OUTER DOOR HANDLE BASE	1	R	\$450.00	✓
50	FRONT RH OUTER DOOR HANDLE	1	Tn	\$380.00	✓
51	FRONT RH OUTER DOOR HANDLE BASE	1		\$450.00	7
52	FRONT SUSPENSION CROSSMEMBER	1		\$5,500.00	7
53	FRONT RH LOWER ARM	1		\$550.00	7
54	FRONT LH LOWER ARM	1		\$550.00	7
55	FRONT STABILIZER BAR	1		\$890.00	7
56	FRONT LH KNUCKLE ARM	1		\$870.00	7
57	FRONT RH KNUCKLE ARM	1		\$870.00	7
58	FRONT LH LOWER ARM BALL JOINT	1		\$250.00	7
59	FRONT RH LOWER ARM BALL JOINT	1		\$250.00	7
60	FRONT LH KNUCKLE HUB + BEARING	1		\$480.00	7
61	FRONT RH KNUCKLE HUB + BEARING	1		\$480.00	7
62	FRONT LH UPPER ARM	1		\$590.00	7
63	FRONT RH UPPER ARM	1		\$590.00	7
64	FRONT LH SUSPENSION SHOCK ABSORBER	1		\$780.00	7
65	FRONT RH SUSPENSION SJOCK ABSORBER	1		\$780.00	7
66	STEERING RACK	1		\$3,900.00	7
67	STEERING WHEEL	1		\$4,890.00	7
68	STEERING COLUMN COVER SET	1	CM	\$3,380.00	✓
69	STEERING WHEEL SPIRAL CABLE	1	R	\$1,945.00	✓
70	FRONT LH SEAT	1	R	\$7,800.00	X
71	FRONT RH SEAT	1	R	\$7,800.00	X
72	FRONT LH OUTER SIDE PANEL	1	R	\$8,900.00	X
73	FRONT RH OUTER SIDE PANEL	1	R	\$8,900.00	✓
74	FRONT LH INNER UPPER PILLAR	1	R	\$3,800.00	X
75	FRONT RH INNER UPPER PILLAR	1	R	\$3,800.00	✓
76	FRONT LH PILLAR LOWER REINFORCEMENT	1	R	\$1,850.00	X

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 19-7-2024
 Vehicle No: GBD8572T
 Model: Nissan NV350
 Chassis: JN1MC2E26Z0004313
 Reg.Year: 10.6.2015

Third Party Insurer: China Taiping
 Third Party Veh No: CB356C
 Date of Accident: 9/7/2024
 Estimator: Loong
 Surveyor:

77	FRONT RH PILLAR LOWER REINFORCEMENT	1		R \$1,850.00	X
78	FRONT LH FOOT STEP PANEL	1		R \$900.00	X
79	FRONT RH FOOT STEP PANEL	1		dit \$900.00	✓
80	FRONT LH FENDER LINER	1		ln \$375.00	X
81	FRONT RH FENDER LINER	1		ln \$375.00	X
82	FRONT BUMPER LICENCE PLATE MOULDING	1		ln \$150.00	X
83	FRONT WIPER GARNISH	1		rd \$980.00	✓
SUB TOTAL				\$164,195.00	
LESS 10%				-\$16,419.50	
PARTS TOTAL				\$147,775.50	

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BUMPER CLIPS	1		ln \$55.00	✓
2	FRONT FENDER LINER CLIPS	1		nn \$50.00	X
3	RADIATOR COOLANT	1		nn \$150.00	X
4	FRONT LICENCE PLATE NUMBER WITH FRAME	1		mi \$60.00	25ln
5	FRONT WINDSCREEN SEALANT	1		ln \$120.00	40ln
6	FRONT WINDSCREEN ERP STICKER	1		ln \$60.00	26ln
7	FRONT WINDSCREEN PRIMER	1		ln \$80.00	30ln
8	FRONT DOOR INNER TRIM BOARD CLIPS	1		ln \$50.00	✓
9	FRONT WIPER GARNISH CLIPS	1		nn \$50.00	X
10	FRONT A PILLAR SEALANT	1		nn \$250.00	X
S/N TOTAL				\$925.00	

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT AND REAR ACCIDENT AREAS

\$7,000.00 3000l

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AFFECTED AREAS

\$7,000.00 2000l

TO REMOVE & REFIX FRONT WINDSCREEN GLASS TO ENABLE BODYWORK REPAIR

\$150.00 120l

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT AND REAR DOOR INNER MECHANISM AND ETC. BACK TO ORIGINAL OPERATIONS.

\$380.00 120l

TO READJUST AND REALIGN HEADLAMP AIM

\$100.00 30l

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 19-7-2024
Vehicle No: GBD8572T
Model: Nissan NV350
Chassis: JN1MC2E26Z0004313
Reg.Year: 10.6.2015

Third Party Insurer: China Taiping
Third Party Veh No: CB356C
Date of Accident: 9/7/2024
Estimator: Loong
Surveyor:

TO TUFF KOTE & UNDERSEAL MATERIALS.

1501
\$300.00

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$280.00 1501

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$150.00 801

TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT

\$150.00 601

TO REMOVE AND REFIT FRONT UNDERCARRIAGE PARTS TO ENABLE BODYWORK REPAIR

\$400.00 ?

MOUNT WORKBENCH - TO REALIGNMENT FRONT CHASSIS AND REPAIR ACCIDENT
AFFECTED AREAS

\$450.00 ?

TO REMOVE AND REFIT FRONT DASHBOARD, FRONT SEAT, REAR LUGGAGE
COMPARTMENT LININGS, GARNISH, COVER, TRIMMINGS TO ENABLE BODYWORK REPAIR

\$350.00 2501

LABOUR TOTAL \$16,710.00

TOTAL \$165,410.50

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: