

*Not Authorised
19/7/24
4/5 of 9810
15 hrs*

PLEASE ARRANGE TO SURVEY
VEHICLE AT 30 BUKIT BATOK
CRESCENT (S 658075)

Selamatshahh
CLAIM DEPARTMENT
DID : 66547617
FAX :

Date : 18/07/2024

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd
SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1 Accident Date : 06/07/2024

Vehicle No : GBE-4699-H Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
Nett Item			
1	REAR BUMPER <i>Dis</i>	732.70 ✓	
2	REAR BUMPER RETAINER <i>MS</i>	351.20 X	
10	REAR BUMPER CLIPS <i>ner</i>	50.00 <i>305/w</i>	
1	END PANEL OUTER <i>304.00</i>	340.00 ✓	
1	END PANEL INNER <i>304.00</i>	420.00 ✓	
1	REAR STEP PANEL <i>304.00</i>	256.40 ✓	
1	FLOOR PANEL <i>cramped/buc</i>	1,980.00 ✓	
1	TAILGATE <i>304.00</i>	2,101.40 ✓	
1	TAILGATE LOCK <i>DD/buc</i>	262.30 ✓	

Date : 18/07/2024

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 06/07/2024

Vehicle No : GBE-4699-H

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
2	TAILGATE STOPPER RH/LH <i>1u</i>	68.00	X
1	TAILGATE WEATHERSTRIPE <i>2u</i>	109.30	✓
1	REAR LOGO <i>5u</i>	64.90	X
1	EMBLEM - NV350 <i>1u</i>	110.00	—
1	EMBLEM - URVAN <i>1u</i>	90.00	—
1	TAILGATE TRIMBOARD <i>70.11</i>	290.00	—
1	TAILGATE HANDLE CHROME <i>11</i>	225.60	X
2	NUMBER PLATE LAMP <i>11</i>	220.00	X
* 2	TAILAMP RH/LH <i>N/S 11 @ 15.50</i>	449.60	IPC 224.80
1	REAR FENDER RH <i>woped/Buc</i>	2,180.00	—

Date : 18/07/2024

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 06/07/2024

Vehicle No : GBE-4699-H

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR FENDER LH <i>n</i>	1,940.00	X
2	REAR FENDER AIRVENT RH/LH <i>0/1 Torn</i>	65 130.00	120
1	REAR EXHAUST SILENCER <i>1H</i> <i>1H</i>	480.00	X
2	REAR EXHAUST MOUNTING <i>17</i>	40.00	X
2	REAR CHASSIS PANEL RH/LH <i>R</i>	RESTORE	X
1	FRONT BUMPER <i>R</i>	617.70	X
2	FRONT BUMPER RETAINER <i>17</i>	351.20	X
10	FRONT BUMPER CLIPS <i>17</i>	50.00	X
1	FRONT BUMPER REINFORCEMENT <i>n</i>	838.20	X
1	FRONT GRILLE <i>17</i>	570.30	X

Date : 18/07/2024

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 06/07/2024

Vehicle No : GBE-4699-H

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT PANEL	RESTORE <i>n</i>	<i>X</i>
2	HEADLAMP RH/LH	<i>o/s change</i> 960.00	<i>X</i>
	Sub Total	16278.80	
	Discount 10% On Parts	(1627.88)	
	<u>Special Nett Item</u>		
1	REVERSE SENSOR	<i>70m</i> 220.00	<i>2005/20</i>
1	REAR WINDSCREEN SEALANT	<i>ner</i> 50.00	<i>40</i>
1	8 PAX STICKER	<i>ner</i> 10.00	<i>/</i>
1	70KM/HR STICKER	<i>ner</i> 10.00	<i>/</i>
1	REAR NUMBER PLATE	<i>pu</i> 35.00	<i>X</i>
	<i>10 pcs Rear bumper clips \$50 ner 305/20</i>		

Date : 18/07/2024

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 06/07/2024

Vehicle No : GBE-4699-H

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	FRONT NUMBER PLATE	<i>35.00</i> 35.00	✓
1	REAR FLOOR WOODEN BOARD	<i>200.00</i> 200.00	✓
	Sub Total	560.00	
<u>Labour & Misc</u>			
	LABOUR TO FACILITATE REPAIR	2,000.00	<i>1800</i>
	TO RESPRAY AFFECTED AREAS	2,000.00	<i>1500</i>
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	120.00	<i>100</i>
	TO REMOVE AND TRANSFER TAILGATE COMPONENTS	100.00	<i>60</i>
	TO REMOVE AND REFIT FUEL TANK ASSY	<i>17</i> 200.00	<i>X</i>

Date : 18/07/2024

To : MS FIRST CAPITAL INSURANCE LIMITED

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : 1

Accident Date : 06/07/2024

Vehicle No : GBE-4699-H

Make & Model : NISSAN NV350 PANEL VAN 2.5 DIESEL G (M)

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO PULL AND REALIGN REAR CHASSIS PANEL	11 300.00	X
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	50.00	30
	RUST PROOFING	100.00	80
	TOWING CHARGES	150.00	X
	Sub Total	5020.00	
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged parts for resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		20,230.92	
		SUB TOTAL	
		GST 9.0 %	1,820.78
		TOTAL	22,051.70

Remarks:

not Acknowledged

Surveyor's name: Marcus Lim

Principal's name: ETHOZ Group Ltd

Survey Date & Time: 18/7/24 @ 9am

2/5 @ 9850
 2/5 @ 9850
 15 days

1-9161.9
 102
 2-8245.71
 5.25
 2-3570
 12345.71
 223
 9872