

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. : SAC2401343

INV Date : 12-11-2024

Reference CD/LPC24070300/Rua3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLP 3988D
Insured Veh. XE 8405C
Claim No. 24/24/24/VC05/029550
Policy No. Z24VC05024424
Accident Date 16/07/2024
Inspection Date 19/07/2024

Description	Amount
Third Party Express Settlement	450.00
Sub-Total	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CD/LPC24070300/Rua3q2
300 BEACH ROAD	Date:	12/11/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	XE 8405C	Veh. Inspected	SLP 3988D
Policy No.	Z24VC05024424	Coverage	0
Claim No.	24/24/24/VC05/029550	Excess	\$0.00
Assign From	-	Assign Date	18/07/2024

2. Vehicle Details

Make & Model	SKODA OCTAVIA RS 2.0 TSI AIDISPLAY	C.C	1984
Engine No.	DLB032482	Year of Reg.	25/09/2020
Chassis No.	TMBBU7NE9L0058106	Colour	YELLOW
Odometer	63253 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/35Z R19	CONTINENTAL	6
L/H Front Tyre	245/35Z R19	CONTINENTAL	6
R/H Rear Tyre	245/35Z R19	CONTINENTAL	6
L/H Rear Tyre	245/35Z R19	CONTINENTAL	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/07/2024	Inspection Date	19/07/2024
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLP 3988D

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	COVER FOR REAR BUMPER (SN)	CRACKED	\$1,656.51	\$1,656.51
1	COVER FOR TOWING COVER (SN)	NOT NECESSARY	\$16.83	\$0.00
1	GUIDE PIEC LHR BUMPER BRACKET (SIDE)(SN)	NOT NECESSARY	\$34.00	\$0.00
1	GUIDE PIEC RHR BUMPER BRACKET (SIDE)(SN)	NOT NECESSARY	\$34.00	\$0.00
1	SENSOR PRIMED (SN)	NOT NECESSARY	\$206.04	\$0.00
4	SEAL RING SATIN BLACK (SN)	NOT NECESSARY	\$6.52	\$0.00
1	SENSOR BRA(SN)	NECESSARY	\$11.35	\$11.35
2	SENSOR BRA (SN)	NECESSARY	\$22.70	\$22.70
1	SENSOR BRA (SN)	NECESSARY	\$11.35	\$11.35
1	2K-PLASTIC ADHESIVE (SN)	NECESSARY	\$94.98	\$94.98
1	BONDING AGENT FOR PLASTIC (SN)	NECESSARY	\$78.24	\$78.24
1	TAILLIGHT RHR (SN)	CRACKED	\$1,098.67	\$1,098.67
1	BULB HOLDE (SN) (ADDITIONAL)	NECESSARY	\$86.70	\$86.70
			\$3,357.89	\$3,060.50

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR		\$280.00	\$280.00
	B&P DIAGNOSIS AND PROGRAMMING		\$480.00	\$480.00
	LABOUR		\$3,360.00	\$1,680.00
	SPRAY PAINTING		\$3,200.00	\$1,600.00
			\$7,320.00	\$4,040.00

GRAND TOTAL			\$10,677.89	\$7,100.50
--------------------	--	--	--------------------	-------------------

	RECOMMENDED COST OF REPAIRS			\$7,100.50
--	------------------------------------	--	--	-------------------

Report Ref No: CD/LPC24070300/Rua3q2

MRB

MOHAMMED RASUL BIN MOHD YUNUS



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933


TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.




PHOTOGRAPHS FOR VEHICLE NO. : SLP 3988D



PHOTOGRAPHS FOR VEHICLE NO. : SLP 3988D



PHOTOGRAPHS FOR VEHICLE NO. : SLP 3988D




PHOTOGRAPHS FOR VEHICLE NO. : SLP 3988D



PHOTOGRAPHS FOR VEHICLE NO. : SLP 3988D




PHOTOGRAPHS FOR VEHICLE NO. : SLP 3988D



PHOTOGRAPHS FOR VEHICLE NO. : SLP 3988D



PHOTOGRAPHS FOR VEHICLE NO. : SLP 3988D







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 3 of 5)

PHOTOGRAPHS FOR VEHICLE NO. : SLP 3988D



PHOTOGRAPHS FOR VEHICLE NO. : SLP 3988D





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 5 of 5)

PHOTOGRAPHS FOR VEHICLE NO. : SLP 3988D



PHOTOGRAPHS FOR VEHICLE NO. : SLP 3988D

