

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0562/2024/KS
DATE : 19-Jul-24
WIP : 23698

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 12/6/2024.

YOUR INSURED VEH NO : SLA 9787 G

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MS ANNE JENG PEIPEY (ANNE ZHENG BEI BEI)
ADDRESS : 45 TOH TUCK ROAD
#03-09
SINGAPORE 596720
TELEPHONE : HP +65 91770881
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 1900252228-02
VEHICLE NO : **SKR 5545 L**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 29/11/2019
ENGINE NO : CZD 886479
CHASSIS NO : WAUZZZF3XL1013739
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Jul-24
PLACE OF ACCIDENT : PIE TOWARDS CITY AREA BEFORE BKE EXIOT, CENTRE LANE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKR 5545 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,000.00	
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING.	\$	2,000.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	
TOTAL LABOUR CHARGES		:	\$	4,652.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKR 5545 L.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,960.00	
2	REAR BUMPER FIXING PARTS	1	\$ 233.00	
3	REAR BUMPER DAMPER - LH / RH	2	\$ 48.00	
4	REAR BUMPER SPOILER	1	\$ 573.00	
5	REAR CROSS REINFORCEMENT - CENTER	1	\$ 121.00	
6	REAR BUMPER BRACKET	1	\$ 60.00	
7	REAR LIGHT REFLECTOR - LH / RH	2	\$ 98.00	
8	REAR PARKING AID SENSOR	2	\$ 572.00	
9	REAR PARKING AID SENSOR SEAL RING	4	\$ 11.00	
10	REAR REINFORCEMENT BEAM	1	\$ 797.00	
11	REAR BUMPER HOLDING STRAP - LH / RH	2	\$ 74.00	
12	REAR WHEEL ARCH COVER - LH / RH	2	\$ 636.00	
13	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 5,683.00	
TOTAL LABOUR CHARGES		:	\$ 4,652.00	
GRAND TOTAL		:	\$ 10,335.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT