

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

not Authorized
in
month
22/7/24
d/s & \$300
Ampl. App. up
4 days

VEHICLE No: SMM 6063G

1PC	REAR WINDSCREEN	11	\$1,655.10 X
1PC	REAR WINDSCREEN MOULDING	25	\$185.50 X
1PC	TAILGATE	1985.90	20/344 \$2,994.45
1PC	TAILGATE OUTER CHROME GARNISH	11	\$688.10 X
1PC	TAILGATE EMBLEM 'Hybrid'	12L	\$68.90
1PC	TAILGATE INNER LOCK	409.90	20/344 \$609.23
1PC	TAILGATE INNER TRIM BOARD	20/344	\$681.20
1PC	TAILGATE INNER PULL GARNISH	11	\$65.20 X
1PC	TAILGATE WEATHERSTRIP	20/344	\$399.45
1PC	TAILGATE KEYLESS SMART	82	\$185.30 X
1PC	REAR BUMPER	985.10	20/344 \$1,655.10
2PCS	REAR BUMPER REFLECTORS @\$145.00	11	\$290.00 X
2PCS	REAR BUMPER SIDE RETAINERS @\$105.10	11	\$210.20 X
1PC	REAR END PANEL	801.10	20/344 \$955.23
1PC	REAR END PANEL TOP GARNISH	285.40	20/344 \$366.10
2PCS	TAILLAMP LOWER APRON GARNISHS @\$385.10	11	\$770.20 X
1PC	REAR FLOOR PANEL	R	\$820.10 X
1PC	REAR FLOOR PANEL TOP BOARD	845.10	11 \$1,282.20
			\$13,881.56

252

S.NETT

1PC	REAR WINDSCREEN SEALANT	12L	\$50.00 40
1PC	REAR WINDSCREEN INNER SEAL	12L	\$50.00 20
1PC	REAR LICENCE PLATE	11	\$50.00 X
1SET	REAR BUMPER LOWER REFLECTIVE STICKER	11	\$180.00 X
1SET	REAR BUMPER CLIPS	12L	\$50.00 30
1SET	TAILGATE INNER TRIM BOARD CLIPS	11	\$50.00 X
1PC	REAR END PANEL SEALANT	12L	\$50.00 40

TO CHECK WIRING	\$50.00 20
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00 20
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00 60
TO TRANSFER TAILGATE MECHANISM	\$100.00 60
TO SPRAY RUST PROOFING	\$100.00 50
TO RESET & REPROGRAMME SYSTEM	11 \$120.00 X

LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$1,500.00	600
	\$1,500.00	800
TOTAL	\$18,001.56	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 6462-05
212
484654
130
1710
668654
202
5349