

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

Not Authorized
in
month
22/7/24
d/s \$5300
through the rep
4 days

VEHICLE No: SMM 6063G

1PC	REAR WINDSCREEN		11	\$1,655.10 X
1PC	REAR WINDSCREEN MOULDING		25	\$185.50 X
1PC	TAILGATE	1985.90	22/24	\$2,994.45 ✓
1PC	TAILGATE OUTER CHROME GARNISH		11	\$688.10 X
1PC	TAILGATE EMBLEM 'Hybrid'		11	\$68.90 ✓
1PC	TAILGATE INNER LOCK	409.90	24/24	\$609.23 ✓
1PC	TAILGATE INNER TRIM BOARD		24/24	\$681.20 ✓
1PC	TAILGATE INNER PULL GARNISH		11	\$65.20 X
1PC	TAILGATE WEATHERSTRIP		211	\$399.45 ✓
1PC	TAILGATE KEYLESS SMART		82	\$185.30 X
1PC	REAR BUMPER	985.10	22/24	\$1,655.10 ✓
2PCS	REAR BUMPER REFLECTORS @\$145.00		11	\$290.00 X
2PCS	REAR BUMPER SIDE RETAINERS @\$105.10		11	\$210.20 X
1PC	REAR END PANEL	801.10	22/24	\$955.23 ✓
1PC	REAR END PANEL TOP GARNISH	285.40	211	\$366.10 ✓
2PCS	TAILLAMP LOWER APRON GARNISHS @\$385.10		11	\$770.20 X
1PC	REAR FLOOR PANEL		R	\$820.10 X
1PC	REAR FLOOR PANEL TOP BOARD	845.10	Che	\$1,282.20 ✓
				\$13,881.56

S.NETT

1PC	REAR WINDSCREEN SEALANT	11	\$50.00 40
1PC	REAR WINDSCREEN INNER SEAL	11	\$50.00 20
1PC	REAR LICENCE PLATE	11	\$50.00 X
1SET	REAR BUMPER LOWER REFLECTIVE STICKER	11	\$180.00 X
1SET	REAR BUMPER CLIPS	11	\$50.00 30
1SET	TAILGATE INNER TRIM BOARD CLIPS	11	\$50.00 X
1PC	REAR END PANEL SEALANT	11	\$50.00 40
			\$50.00 20
TO CHECK WIRING			\$150.00 120
TO DISMANTLE & REFIX REAR WINDSCREEN			\$120.00 60
TO DISMANTLE & REFIX CUSHION UPHOLSTERY			\$100.00 60
TO TRANSFER TAILGATE MECHANISM			\$100.00 50
TO SPRAY RUST PROOFING			\$120.00 X
TO RESET & REPROGRAMME SYSTEM			

LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

	\$1,500.00	600
	\$1,500.00	800
TOTAL	\$18,001.56	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 6462-05
222
4846.54
130
1710
6686.54
202
5349