

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0561/2024/KS
DATE : 19-Jul-24
WIP : 23956

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 24/07/2024.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR.WONG JUN MING (HUANG JUNMING)
ADDRESS : 70 SHENTON WAY
#31-07
SINGAPORE 079118
TELEPHONE : HP +65 97854683
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210081351-02
VEHICLE NO : **SNA 9896 B**
MODEL CODE : A4 2.0 TFSI S TRONIC
MODEL YEAR : 27/7/2021
ENGINE NO : DEM 028960
CHASSIS NO : WAUZZZF47MA025311
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Jul-24
PLACE OF ACCIDENT : LEFT TURN SLIPROAD, AFTER CTE EXIT TO YIO CHU KANG
TOWARDS THOMSON ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNA 9896 B.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER.	S/N \$	480.00 250 ✓ ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$	700.00 250 ✓	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00 1000 ✓	
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	2,000.00 1000 ✓	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00 ✓ ✓	
TOTAL LABOUR CHARGES		:	\$ 5,572.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SNA 9896 B.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>damaged</i>	1	\$ 2,670.00	<i>✓ 2136</i>
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 420.00	<i>✓</i>
3	FRONT BUMPER SECURING STRIP <i>new</i>	2	\$ 90.00	<i>+</i>
4	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 245.00	<i>+</i>
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	1	\$ 329.00	<i>✓ 267.80</i>
6	FRONT BUMPER AIR GUIDE - LH / RH <i>new</i>	2	\$ 176.00	<i>7 ✓</i>
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>cracked</i>	1	\$ 329.00	<i>7 ✓ 262.80</i>
8	FRONT BUMPER AIG GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 338.00	<i>7 ✓</i>
9	RADIATOR GRILLE <i>cracked</i>	1	\$ 1,949.00	<i>✓ 1559.20</i>
10	"CAUTION" STICKER <i>new</i>	1	\$ 25.00	<i>✓ 19.44</i>
11	"A/C" STICKER <i>new</i>	1	\$ 10.00	<i>✓ 7.52</i>
12	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 92.00	<i>+</i>
13	FRONT BUMPER TOP BRACKET <i>cracked</i>	1	\$ 173.00	<i>7 138</i>
14	FRONT FOAM FILLER PIECE <i>cracked</i>	1	\$ 237.00	<i>7 189.60</i>
15	FRONT REINFORCEMENT BEAM <i>cracked</i>	1	\$ 1,033.00	<i>7 826.40</i>
16	FRONT BUMPER TOP BRACKET SUPPORT - LH / RH <i>cracked</i>	2	\$ 74.00	<i>7 57.76</i>
17	LED HEADLIGHT - LH / RH <i>LH cracked</i>	2	\$ 18,408.00	<i>9206 1363.20</i>
18	LED HEADLIGHT SPACER - LH / RJ <i>new</i>	3	\$ 150.00	<i>7 ✓</i>
19	LIFT CYLINDER - LH / RH <i>2 new</i>	2	\$ 504.00	<i>+</i>
20	LIFT CYLINDER BRACKET - LH / RH <i>new</i>	2	\$ 16.00	<i>+</i>
SUB TOTAL SPARE PARTS		:	\$ 27,268.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNA 9896 B.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LIFT CYLINDER HOSE <i>2nd new</i>	1	\$ 118.00	X
22	HEADLIGHT TOP COVER - LH / RH <i>2nd new</i>	2	\$ 110.00	X <i>43.44</i>
23	BONNET <i>Dented</i>	1	\$ 3,470.00	X <i>2776</i>
24	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 460.00	X
25	BONNET HINGE - LH / RH <i>new</i>	2	\$ 744.00	X
26	BONNET IMPACT PROTECTION - CENTER <i>new</i>	1	\$ 36.00	X <i>28.40</i>
27	BONNET IMPACT PROTECTION - LH / RH <i>new</i>	2	\$ 70.00	X <i>56.80</i>
28	BONNET STRIKER - LH / RH <i>new</i>	2	\$ 126.00	X
29	BONNET LID LOCK - LH / RH <i>new</i>	2	\$ 491.00	X
30	BONNET BOWDEN CABLE - CENTER <i>new</i>	1	\$ 71.00	X
31	BONNET BOWDEN CABLE <i>new</i>	1	\$ 71.00	X
32	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	X <i>60</i>
33	SUNDRIES <i>new</i>		\$ 600.00	X <i>36.16</i>
TOTAL SPARE PARTS		:	\$ 33,695.00	
TOTAL LABOUR CHARGES		:	\$ 5,572.00	
GRAND TOTAL		:	\$ 39,267.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ls*
SURVEYED DATE : *24/07/24*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT