



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SGT 9921U

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRT BUMPER	DEFORMED	\$2,867.65	\$2,650.00
1	FRT BUMPER SIDE RETAINER RH	NOT NECESSARY	\$78.90	\$0.00
1	HEAD LAMP RH	CUT	\$1,282.90	\$1,050.00
1	FRT SIGNAL LAMP RH	CUT	\$762.35	\$550.00
1	FRT FENDER INNER SHIELD RH	NOT NECESSARY	\$273.25	\$0.00
1	FRT FENDER RH	TO REPAIR SEE LABOUR	\$1,253.50	\$0.00
	LESS 10.00% DISCOUNT		(\$651.86)	(\$425.00)
			\$5,866.69	\$3,825.00

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRT BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$30.00
1	FRT NUMBER PLATE & HOLDER (SN)	NOT NECESSARY	\$40.00	\$0.00
1	FRT BUMPER STICKER (SN)	NOT NECESSARY	\$100.00	\$0.00
			\$190.00	\$30.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF FRT FENDER RH		\$800.00	\$300.00
	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS		\$100.00	\$30.00
	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED		\$800.00	\$400.00
	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	NOT NECESSARY	\$50.00	\$0.00
	TO VACUUM, WAXING & CLEAN	NOT NECESSARY	\$50.00	\$0.00
	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	NOT NECESSARY	\$60.00	\$0.00
			\$1,860.00	\$730.00

GRAND TOTAL	\$7,916.69	\$4,585.00
--------------------	-------------------	-------------------

RECOMMENDED COST OF REPAIRS		\$4,585.00
------------------------------------	--	-------------------

Report Ref No: CS/LIP24070305/Tnh3m4

MARKET VALUE: \$30,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$14,104.00=NETT VALUE: \$15,896.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

MTH

MOHAMAD TAUFIKH

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.