



Century Motors

Century Motors (Singapore) Pte Ltd  
6 Marsiling Lane  
Singapore 739145



E: claims@autoinsure.com.sg

T: (65) 3157 2626

**GST No.: 192800002R**

**Page No.1**

**AUTOMOBILE ASSESSMENT REPORT**

Our Ref: **SGT9921U**  
Your ref: **GBG8194K**

Date: **16-Jul-23**

BY EMAIL ONLY  
(claims@autoinsure.com.sg)

**ATTENTION: MOTOR CLAIMS DEPT**

**LIBERTY INSURANCE PTE LTD**

51 CLUB STREET  
#03-00 LIBERTY HOUSE  
SINGAPORE : 069428

Assessed Vehicle No : **SGT9921U**  
Car Make and Model : **DAIHATSU COPEN 660 A**  
Date of Accident : **8-Jul-23**  
Date of Assessment : **9-Jul-23**

We have carried out a physical assessment of SGT9921U at our workshop Century Motors (Singapore) Pte Ltd sustained damages to the FRONT portion of the vehicle.


**4. DESCRIPTION OF DAMAGE**

At the time of the inspection observed that this vehicle had sustained damages to the FRONT portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : **P/P**  
Adjusted Amount : **\$ 2,214.00**  
Est. Repair Days : **7**



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.  
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

**Disclaimer**

This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.

No liability or responsibility whatsoever shall be held by

**Century Motors (Singapore) Pte Ltd** For any reliance on this report by any third party.

Our Ref: SGT9921U

Your Ref: GBG8194K

| S/NO                                  | QTY | DESCRIPTIONS                           | ASSESSED<br>CONDITION | EST. BY WORKSHOP |
|---------------------------------------|-----|--|-----------------------|------------------|
| <b>PARTS REPLACEMENT - LIST ITEMS</b> |     |  |                       |                  |
| 1                                     | 1   | FRT BUMPER <i>del</i>                  |                       | 2650 \$2867.65   |
| 2                                     | 1   | FRT BUMPER SIDE RETAINER RH <i>Xnn</i> |                       | \$78.90          |
| 3                                     | 1   | HEAD LAMP RH <i>cut</i>                |                       | 1050 \$1282.90   |
| 4                                     | 1   | FRT SIGNAL LAMP RH <i>cut</i>          |                       | 550 \$762.35     |
| 5                                     | 1   | FRT FENDER INNER SHIELD RH <i>Xnn</i>  |                       | \$273.25         |
| 6                                     | 1   | FRT FENDER RH <i>Rp</i>                |                       | \$1253.50        |
|                                       |     |  | SUB TOTAL             | \$ 4250 -        |
|                                       |     |  | LESS 10%              | \$ 10/ 3825 -    |
|                                       |     |  | TOTAL AMOUNT          | \$ -             |

Our Ref: SGT9921U

Your Ref: GBG8194K

| S/NO | QTY | SPECIAL NETT ITEMS        | ASSESSED<br>CONDITION | EST. BY WORKSHOP |
|------|-----|---------------------------|-----------------------|------------------|
| 1    | 1   | FRT BUMPER CLIPS          |                       | \$ 300 50.00     |
| 2    | 1   | FRT NUMBER PLATE & HOLDER |                       | \$ nn X 40.00    |
| 3    | 1   | FRT BUMPER STICKER        |                       | \$ nn X 100.00   |
|      |     |                           | SUB TOTAL             | \$ 190.00        |
|      |     |                           | TOTAL PARTS COST      | \$ 30 190.00     |

Our Ref: SGT9921U

Your Ref: GBG8194K

| S/NO                          | DESCRIPTION  | EST. BY WORKSHOP |
|-------------------------------|--|------------------|
| <b>LABOUR &amp; PAINTWORK</b> |  |                  |
| 1                             | TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;<br>PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE<br>DAMAGED PARTS AND COMPONENTS | \$ 300 800.00    |
| 2                             | TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER<br>FUNCTIONS  | \$ 30 100.00     |
| 3                             | TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED   | \$ 400 800.00    |
| 4                             | SUNDRIES (SAND PAPER, WELDING WIRE ETC.)   | \$ nn X 50.00    |
| 5                             | TO VACUUM, WAXING & CLEAN  | \$ nn X 50.00    |
| 6                             | TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS   | \$ nn X 60.00    |
|                               | TOTAL BEFORE GST   | \$ 730 2,050.00  |
|                               | GST 8%   | \$ 164.00        |
|                               | TOTAL (PARTS & LABOUR):  | \$ 2,214.00      |

#### Adjustments / Recommendations

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$ - for lump sum with the third party insurance.

Yours Faithfully,  
  
Ck Loh  
Claims Estimator

Acknowledged by Repairer  
Signature:  
Date:

*Tanfikh 92495745*  
*wp 19/7/24 @ 320pm*  
*Tanfikh e lkh auto.com*  
*P/P Resury before paint*  
*No end hand part*

3825  
30  
730  
\$4585  
3 days  
\*