

**AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.**

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)
Tel : 6702 1555 Fax : 6702 1444
Co. Reg No. : 201500047H GST No. : 201500047H
Email : st.sim@autobacs.com.sg

TO	: Liberty (SNJ4901E)	DATE	: 18-Jul-24
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX723Z	P -	
		S -	
		L -	
VEHICLE DETAILS			
VEHICLE NO.	: SLB6242B	TOTAL	:
MODEL / MAKE	: Nissan X-Trail	L/S -20%	:
CHASSIS NO.	: JN1JANT32Z0001685	SUB TOTAL	:
ACCIDENT DETAIL			
DATE	: 17-Jul-24		
TIME	: 06:32HRS	CONTACT PERSON	: MR. SIM 9844 0974

QUOTATION SUMMARY

PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT NETT PRICE	TOTAL NETT PRICE
1	Rear fender Rh / <i>DD</i>	1	\$ 1,097.40	\$ 1,097.40
2	Rear fender quarter glass with moulding Rh <i>X</i> nn	1	\$ 894.30	\$ 894.30
3	Rear fender arch garnish Rh / <i>CU</i>	1	\$ 195.30	\$ 195.30
4	Rear fender inner shield Rh / <i>CR4</i>	1	\$ 186.40	\$ 186.40
5	Rear fender inner air vent Rh / <i>BR</i>	1	\$ 89.40	\$ 89.40
6	Rear fender inner trim board Rh <i>X</i> nn	1	\$ 552.60	\$ 552.60
7	Rear bumper / <i>BR</i>	1	\$ 771.80	\$ 771.80
8	Rear bumper reflector Rh <i>X</i> nn	1	\$ 65.50	\$ 65.50
9	Rear bumper inner sponge <i>X</i> nn	1	\$ 173.40	\$ 173.40
10	Rear bumper reinforcement <i>X</i> nn	1	\$ 663.20	\$ 663.20
11	Rear bumper reinforcement bracket Lh <i>X</i> nn	1	\$ 217.90	\$ 217.90
12	Rear bumper reinforcement bracket Rh <i>X</i> nn	1	\$ 217.90	\$ 217.90
13	Rear bumper side retainer Lh <i>X</i> nn	1	\$ 55.90	\$ 55.90
14	Rear bumper side retainer Rh / <i>BR</i>	1	\$ 55.90	\$ 55.90
15	Rear bumper corner retainer Lh <i>X</i> nn	1	\$ 43.30	\$ 43.30
16	Rear bumper corner retainer Rh <i>X</i> nn	1	\$ 43.30	\$ 43.30
17	Rear end panel <i>X</i> <i>R</i>	1	\$ 498.70	\$ 498.70
TOTAL PRICE				\$ 5,822.20
LESS -10%				\$ (582.22)
SUB TOTAL PRICE				\$ 5,239.98

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	Rear fender sealant Rh / <i>MC</i>	1	\$ 120.00	\$ 30 120.00
2	Rear fender quarter glass sealant with primer set Rh / <i>MC</i>	1	\$ 80.00	\$ 20 80.00
3	Rear fender arch garnish clips set Rh / <i>MC</i>	1	\$ 50.00	\$ 20 50.00
4	Rear fender inner trim board clips set Rh <i>X</i> nn	1	\$ 60.00	\$ 60.00
5	Rear bumper clips set / <i>MC</i>	1	\$ 80.00	\$ 30 80.00
6	Rear bumper reverse sensor set / <i>MC</i> / <i>with Defective d</i>	1	\$ 280.00	\$ 280.00
7	Rear end panel sealant <i>X</i> nn	1	\$ 120.00	\$ 120.00
8	Rear end panel top garnish clips set <i>X</i> nn	1	\$ 60.00	\$ 60.00

TOTAL**\$ 850.00**

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,600.00	1000	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA <i>panel white</i>	\$ 1,250.00	900	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 125.00	30	
TO PERFORM LIGHTING & WIRING CHECK	\$ 100.00	30	
TO DISMANTLE & REINSTALL REAR FENDER QUARTER GLASS RH PERFORM	\$ 120.00	80	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 150.00	30	
TO DISMANTLE & REINSTALL INTERIOR CARPET AND REAR 3RD ROLL SEAT WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	80	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 250.00	X nn	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 100.00	30	

TOTAL \$ 3,975.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,089.98
 TOTAL LABOUR COST : \$ 3,975.00
 TOTAL REPAIR COST : \$ 10,064.98

APPROVED DETAILS

NO. OF REPAIR DAYS : 7 DAYS
 REPAIR UNDER : PART BY PART OR LUMP SUM
 DATE / TIME OF SURVEY : m m
 SURVEYED BY / FROM : My AL My
 CONTACT NUMBER :
 EMAIL ADDRESS :
 DATE / TIME OF RE-SURVEY :

Steve (LKK)

19/7/24, 11.00 am

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____