

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 15.07.2024

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNK4790C**
MODEL : **BMW 520D**
DATE OF ACCIDENT : 14.07.2024
TIME OF ACCIDENT : 01:38 HOURS

WBAJC32060G864713

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>del</i>	1	\$ 1,690.80	\$ 1,690.80
2	FRONT BUMPER TOWING COVER <i>del</i>	1	\$ 59.85	\$ 59.85
3	FRONT BUMPER SIDE BOTTOM COVER GARNISH <i>del</i>	2	\$ 276.65	\$ 553.30
4	FRONT CAMERA <i>new</i>	1	\$ 1,308.45	\$ 1,308.45
5	FRONT GRILLE C/W CHROME <i>could</i>	2	\$ 395.85	\$ 791.70
6	FRONT ACTIVE GRILLE AIR SHUTTLE <i>could</i>	1	\$ 498.60	\$ 498.60
7	FRONT ACTIVE GRILLE AIR SHUTTLE MOTOR <i>HP</i>	1	\$ 589.30	\$ 589.30
8	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 218.60	\$ 218.60
9	FRONT BUMPER SIDE GRILLE <i>new</i>	2	\$ 169.70	\$ 339.40
8	FRONT BUMPER SIDE INNER SUPPORT BRACKET <i>new</i>	2	\$ 254.55	\$ 509.10
9	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 865.00	\$ 865.00
10	FRONT BUMPER SPONGE <i>could</i>	1	\$ 254.50	\$ 254.50
11	FRONT BUMPER LOWER BEAM <i>2sp</i>	1	\$ 197.35	\$ 197.35
12	FRONT BUMPER LOWER BEAM GARNISH <i>new</i>	1	\$ 132.90	\$ 132.90
13	FRONT BUMPER FOGLAMP (LED) <i>RH can</i>	2	\$ 471.40	\$ 942.80
14	FRONT BUMPER FOGLAMP UPPER MOULDING <i>new</i>	2	\$ 116.45	\$ 232.90
15	FRONT BUMPER SENSOR <i>new</i>	2	\$ 215.60	\$ 431.20
16	FRONT BUMPER SENSOR HOLDER <i>new</i>	6	\$ 68.00	\$ 408.00
18	HEADLAMP <i>RH could</i>	2	\$ 4,879.55	\$ 9,759.10
19	HEADLAMP TOP RUBBER <i>new</i>	2	\$ 27.40	\$ 54.80

1520
710
471.42
4210
4879.55

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNK4790C**
 MODEL : **BMW 520D**
 DATE OF ACCIDENT : 14.07.2024
 TIME OF ACCIDENT : 01:38 HOURS

20	HEADLAMP LOWER BRACKET	2	\$ 114.80	\$ 229.60
21	HEADLAMP LOWER GARNISH	2	\$ 117.95	\$ 235.90
22	HEADLAMP TOP COVER GARNISH	2	\$ 196.70	\$ 393.40

7724.35 TOTAL PRICE \$ 20,696.55
 7338.13 LESS 5% \$ 1,034.83
SUB TOTAL PRICE \$ 19,661.72

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-1	FRONT NUMBER PLATE	1	\$ 50.00	\$ 50.00
0	FRONT BUMPER CLIP (SET)	1	\$ 49.00	\$ 49.00
1	FRONT BUMPER WRAPPING (SPECAIL TYPE)	1	\$ 850.00	\$ 850.00
2	FRONT BUMPER SIDE BOTTOM COVER GARNISH RH CLIP (SET)	1	\$ 30.00	\$ 30.00
3	ENGINE UNDERCOVER CLIP (SET)	1	\$ 50.00	\$ 50.00
4	FRONT FENDER INNER COWLING CLIP (SET)	1	\$ 50.00	\$ 50.00

349

TOTAL \$ 1,079.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	300
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	200
3	TUFF COAT	\$ 250.00	X
4	WIRING CHECK	\$ 250.00	30
5	REFOCUS HEADLAMP BEAM	\$ 80.00	X
6	REMOVE AND REFIX FRONT CAMERA AND DISTANCE SETTING	\$ 180.00	50
7	REMOVE AND REFIX FRONT SENSOR AND DISTANCE SETTING	\$ 80.00	50

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNK4790C**
MODEL : **BMW 520D**
DATE OF ACCIDENT : 14.07.2024
TIME OF ACCIDENT : 01:38 HOURS

8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 850.00	✕
---	--	-----------	---

630

TOTAL \$3,890.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 20,740.72
TOTAL LABOUR COST : \$ 3,890.00
TOTAL REPAIR COST : \$ 24,630.72

Adrian Cj
h/s 16/07/24.
03 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP :8297 9787

total: 8317.13

h/s: 66K

6.6K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: