

REF:

ASSIGNMENT

From: _____ Date: _____
 Estn: _____
 OD / TP / RES / OD RES / EVA / INV / MV
 To in Vehicle No: _____
 at W/O 100 m/s
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client Record)
 Make of Veh: _____
 (Policy Condition)

N/S	O/S

Remark: Veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SNK4706 Yr Regn: 2017, April
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: BMW 520D C.D. 1995
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 177389 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBAJC32060 G8 64713
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or _____
 Brake: Order / Jammed / Leaked / Burnt or _____
 Mod: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 245/40R19
 R: 245/40R19

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 16/07/24
 Survey held at HD Perfect
 Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP 1st Cap.</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV : 95K</u>
	<u>PV : 44.4K</u>
	<u>Nett : 50.6K</u>

Date/Time, File Pass to? ☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Date/Time, File Return to? _____

2)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Transportation: _____

3 + RS. SI _____

Photos _____

Others _____

Report Format: _____


Report No. A.P.P. P.C.

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 15.07.2024

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNK4790C**
MODEL : **BMW 520D**
DATE OF ACCIDENT : 14.07.2024
TIME OF ACCIDENT : 01:38 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>del d</i>	1	\$ 1,690.80	\$ 1,690.80
2	FRONT BUMPER TOWING COVER <i>del d</i>	1	\$ 59.85	\$ 59.85
3	FRONT BUMPER SIDE BOTTOM COVER GARNISH <i>del d</i>	2	\$ 276.65	\$ 553.30
4	FRONT CAMERA <i>del</i>	1	\$ 1,308.45	\$ 1,308.45
5	FRONT GRILLE C/W CHROME <i>could</i>	2	\$ 395.85	\$ 791.70
6	FRONT ACTIVE GRILLE AIR SHUTTLE <i>could</i>	1	\$ 498.60	\$ 498.60
7	FRONT ACTIVE GRILLE AIR SHUTTLE MOTOR <i>HP</i>	1	\$ 589.30	\$ 589.30
8	FRONT BUMPER LOWER GRILLE <i>del</i>	1	\$ 218.60	\$ 218.60
9	FRONT BUMPER SIDE GRILLE <i>del</i>	2	\$ 169.70	\$ 339.40
8	FRONT BUMPER SIDE INNER SUPPORT BRACKET <i>del</i>	2	\$ 254.55	\$ 509.10
9	FRONT BUMPER REINFORCEMENT <i>del</i>	1	\$ 865.00	\$ 865.00
10	FRONT BUMPER SPONGE <i>could</i>	1	\$ 254.50	\$ 254.50
11	FRONT BUMPER LOWER BEAM <i>2sp</i>	1	\$ 197.35	\$ 197.35
12	FRONT BUMPER LOWER BEAM GARNISH <i>del</i>	1	\$ 132.90	\$ 132.90
13	FRONT BUMPER FOGLAMP (LED) <i>RH can</i>	2	\$ 471.40	\$ 942.80
14	FRONT BUMPER FOGLAMP UPPER MOULDING <i>del</i>	2	\$ 116.45	\$ 232.90
15	FRONT BUMPER SENSOR <i>del</i>	2	\$ 215.60	\$ 431.20
16	FRONT BUMPER SENSOR HOLDER <i>del</i>	6	\$ 68.00	\$ 408.00
18	HEADLAMP <i>RH could</i>	2	\$ 4,879.55	\$ 9,759.10
19	HEADLAMP TOP RUBBER <i>del</i>	2	\$ 27.40	\$ 54.80

Handwritten notes and calculations on the right side of the table:

- Vertical list of symbols: /, /, +, +, /, +, +, +, +, +, +, +, +, +, +, +, +, +, X
- Calculation: 471.40
- Calculation: 4879.55

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNK4790C**
 MODEL : **BMW 520D**
 DATE OF ACCIDENT : 14.07.2024
 TIME OF ACCIDENT : 01:38 HOURS

20	HEADLAMP LOWER BRACKET	2	\$ 114.80	\$ 229.60
21	HEADLAMP LOWER GARNISH	2	\$ 117.95	\$ 235.90
22	HEADLAMP TOP COVER GARNISH	2	\$ 196.70	\$ 393.40

TOTAL PRICE \$ 20,696.55
 LESS 5% \$ 1,034.83
SUB TOTAL PRICE \$ 19,661.72

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
-1	FRONT NUMBER PLATE	1	\$ 50.00	\$ 50.00
0	FRONT BUMPER CLIP (SET)	1	\$ 49.00	\$ 49.00
1	FRONT BUMPER WRAPPING (SPECAIL TYPE)	1	\$ 850.00	\$ 850.00
2	FRONT BUMPER SIDE BOTTOM COVER GARNISH RH CLIP (SET)	1	\$ 30.00	\$ 30.00
3	ENGINE UNDERCOVER CLIP (SET)	1	\$ 50.00	\$ 50.00
4	FRONT FENDER INNER COWLING CLIP (SET)	1	\$ 50.00	\$ 50.00

TOTAL \$ 1,079.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	300
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	200
3	TUFF COAT	\$ 250.00	X
4	WIRING CHECK	\$ 250.00	30
5	REFOCUS HEADLAMP BEAM	\$ 80.00	X
6	REMOVE AND REFIX FRONT CAMERA AND DISTANCE SETTING	\$ 180.00	50
7	REMOVE AND REFIX FRONT SENSOR AND DISTANCE SETTING	\$ 80.00	50

TO : **MS FIRST CAP** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNK4790C**
MODEL : **BMW 520D**
DATE OF ACCIDENT : **14.07.2024**
TIME OF ACCIDENT : **01:38 HOURS**

8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 850.00	<i>✓</i>
---	--	-----------	----------

TOTAL

\$3,890.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 20,740.72
TOTAL LABOUR COST : \$ 3,890.00
TOTAL REPAIR COST : \$ 24,630.72

Adrian G
h/s 16/07/24.
03 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP :8297 9787