



VAG Singapore Pte Ltd
48 Toh Guan Road East
#05-135, Enterprise Hub
Singapore 608586

Tel: 6515 9515
claims@vag.sg
www.avantage.sg

Date : 22-Aug-2024

Vehicle No : SLG4950C

Make/Model : VW GOLF 1.4 TSI

Chassis No : WVVZZZAUZHW056274

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear tailgate	1	\$ 1,590.30	\$ 1,590.30
2	Rear tailgate lock with micro switch	1	\$ 1,403.92	
3	Rear tailgate emblem (golf)	1	\$ 73.95	\$ 73.95
4	Rear tailgate emblem (tsi)	1	\$ 63.45	\$ 63.45
5	Rear taillamp (inner) Rh	1	\$ 498.80	\$ 498.80
6	Rear taillamp (outer)Rh	1	\$ 532.85	\$ 532.85
7	Rear bumper	1	\$ 923.45	\$ 923.45
8	Rear bumper towing cover	1	\$ 40.00	
9	Rear bumper lower spoiler/diffuser	1	\$ 551.25	\$ 551.25
10	Rear bumper parking sensors	2	\$ 145.00	
	SUPPLEMENTARY ITEMS			
1	Rear taillamp (outer) Lh		\$ 520.52	\$ 520.52
2	Rear bumper bracket (center)		\$ 79.43	\$ 79.43
	TOTAL PARTS			\$ 4,834.00
	List Less 10%			\$ 483.40
	TOTAL AMOUNT		\$ -	\$ 4,350.60
	MISCELLANEOUS ITEM			
1	Tuff kote		\$ 50.00	\$ 30.00
2	Rear bumper clips	10	\$ 5.00	\$ 30.00
3	Rear number plate with holder (Red plate)	1	\$ 35.00	\$ 35.00
4	LTA break and reseal fee	1	\$ 150.00	\$ 45.78
	LABOUR			
1	Surface preparation, spray painting of rear bumper, rear tailgate and other affected area		\$ 900.00	\$ 500.00
2	Perform wiring system, connector and diagnostic system check		\$ 100.00	\$ 60.00
3	Workmanship to carry out repair work, remove and assembly, rear bumper, rear tailgate and other affected area		\$ 900.00	\$ 500.00
4	Remove and refit rear windscreen glass to assist repair		\$ 180.00	\$ 120.00
5	Remove and refit reverse sensor to assist repair		\$ 20.00	\$ 20.00
6	Supp - Rear end panel beating		\$ 250.00	\$ 250.00
7	Supp - Respray rear end panel		\$ 250.00	\$ 250.00
	TOTAL			\$ 6,191.38
	GST 9%			\$ 557.22
	GRAND TOTAL			\$ 6,748.60