

(08/11/13) wef

ASS. REC. BY:

REF: CS/CTI24070309/Rvp3

637A

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SLG 4950C

at Workshop m/s AVANTAGE

of TOH GUAN #05-135

Insured:

CTI

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

35K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLG 4950C

Yr Regn:

2016 / 156P

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Golf 1.4 T4 R-L c.c 1395

Colour

Red

AC: Insured / Std / NI / NA

Sp. Reading

104249

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVW222AUZH W056274

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/35R19

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/07/24

D.O.I.

22/07/24

Survey held at

TOH GUAN

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Repair Limit - 16hr

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

\$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Date : 17-Jul-2024

Vehicle No : SLG4950C

Make/Model : VW GOLF 1.4 TSI

Chassis No : WVWZZZAUZH056274

S/N	PARTS	QTY	PRICE	TOTAL
1	Rear tailgate <i>bt</i>	1	\$ 1,590.30	\$ 1,590.30
2	Rear tailgate lock with micro switch <i>X</i>	1	\$ 1,403.92	\$ 1,403.92
3	Rear tailgate emblem (golf) <i>ne</i>	1	\$ 73.95	\$ 73.95
4	Rear tailgate emblem (tsi) <i>ne</i>	1	\$ 63.45	\$ 63.45
5	Rear taillamp (inner) Rh <i>cm</i>	1	\$ 498.80	\$ 498.80
6	Rear taillamp (outer) Rh <i>cm</i>	1	\$ 532.85	\$ 532.85
7	Rear bumper <i>cm</i>	1	\$ 923.45	\$ 923.45
8	Rear bumper towing cover <i>X</i>	1	\$ 40.00	\$ 40.00
9	Rear bumper lower spoiler/diffuser <i>sm</i>	1	\$ 551.25	\$ 551.25
10	Rear bumper parking sensors <i>?</i>	2	\$ 145.00	\$ 290.00
TOTAL PARTS				\$ 5,967.97
List Less 10%				\$ (596.80)
TOTAL AMOUNT				\$ 5,371.17
MISCELLANEOUS ITEM				
1	Tuff kote <i>ne</i>		\$ 50.00	\$ 50.00 <i>30</i>
2	Rear bumper clips <i>ne</i>	10	\$ 5.00	\$ 50.00 <i>30</i>
3	Rear number plate with holder (Red plate) <i>bt</i>	1	\$ 35.00	\$ 35.00
4	LTA break and reseal fee <i>? invoice</i>	1	\$ 150.00	\$ 150.00
LABOUR				
1	Surface preparation, spray painting of rear bumper, rear tailgate and other affected area		\$ 900.00	\$ 900.00 <i>500</i>
2	Perform wiring system, connector and diagnostic system check		\$ 100.00	\$ 100.00 <i>60</i>
3	Workmanship to carry out repair work, remove and assembly, rear bumper, rear tailgate and other affected area		\$ 900.00	\$ 900.00 <i>500</i>
4	Remove and refit rear windscreen glass to assist repair		\$ 180.00	\$ 180.00 <i>120</i>
5	Remove and refit reverse sensor to assist repair		\$ 20.00	\$ 20.00
TOTAL				\$ 7,756.17
GST 9%				\$ 698.06
GRAND TOTAL				\$ 8,454.23

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

From
Hp 90010068
5 days
P/P
22/07/24
Resurvey & paint

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 637A

Vehicle Details

Vehicle No.: SLG4950C

Vehicle to be Exported: No

Intended Deregistration Date: 15 Jul 2024

Vehicle Make: VOLKSWAGEN

Vehicle Model: GOLF 1.4 TSI R-LINE AT SR

Primary Colour: Red

Manufacturing Year: 2016

Engine No.: CZD625909

Chassis No.: WVVZZZAUZHW056274

Maximum Power Output: 110.0 kW (147 bhp)

Open Market Value: \$25,045.00

Original Registration Date: 30 Sep 2016

First Registration Date: 30 Sep 2016

Transfer Count: 0

Actual ARF Paid: \$17,063.00

OPC Cash Rebate Details

OPC Cash Rebate Eligibility: No

OPC Cash Rebate Eligibility Expiry Date: -

OPC Cash Rebate Amount: -

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 29 Sep 2026

PARF Rebate Amount: \$10,237.00

Intended COE Rebate Details

COE Expiry Date: 29 Sep 2026

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$38,501.00

COE Rebate Amount: \$8,491.00

Total Rebate Amount: \$18,728.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 15 Jul 2024

OK