

ASS. REC. BY:

REF:

CD / C72/24070311/KMA3

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HB 78332

Yr Regn:

03, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Prius

C.G.

1798

Colour

N.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

656457

T/Radio:

Insured / Std / NI / NA

Eng/No:

7

C/No:

JDKB 3FU 703 079633

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size:

F: Wgali

195/5R15

R: Saitun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

7

mm

Rear

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

16/7/24

D.O.I.

18/7/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S / R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

19/7 11:00 @ 36000 Cahr

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Not Authorized
11 Bny @ 3600h

Trans-cab Auto Services Pte Ltd

AAD2407-066

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7833L

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

10 JUL 2024

SHB7833L

JTDKB3FU703079633

200303878K

TOYOTA

PRIUS

16/7/2024

SNM 61862/China

29/3/2019

PART

- 1 COVER, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 MIRROR ASSY, OUTER REAR VIEW, LH
- 1 LINER, FRONT FENDER, LH
- 1 FENDER SUB-ASSY, FRONT LH
- 1 FRONT FENDER EMBLEM LH
- 1 RIM
- 1 LAMP ASSY, FOG, LH
- 1 UNIT ASSY, HEADLAMP, LH
- 1 MOULDING ASSY, BODY ROCKER PANEL, LH

LIST

\$	Bu	653.31	✓
\$	su	100.17	X
\$	n	902.16	X
\$	Dis	100.49	✓
\$	n	59.85	X
\$	n	1,695.65	X
\$	su	255.36	X
\$	Bu	1,236.69	✓
\$	n	68.88	✓
\$	su	2,554.70	✓
\$	su	1,200.78	X
\$	su	3,325.56	X
\$	su	624.54	X

TOTAL \$ 12,778.14

25% \$ 3,194.53

\$ 9,583.60

Special Nett

- 1 TYRE
- 1SET CLIP, ROCKER PANEL MOULDING
- 1 FRT BUMPER CLIP
- 1SET FENDER CLIP
- 1 FENDER LINER CLIP

\$	su	350.00	X
\$	su	65.00	X
\$	su	65.00	65.00
\$	su	130.00	X
\$	su	65.00	X

TOTAL \$ 675.00

Trans-cab Auto Services Pte Ltd**AAD2407-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7833L

TOTAL PARTS	\$	2,300.00
--------------------	-----------	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	30%
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	40%
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	44%
To transfer of tire, rim and on wheel balancing.	\$	170.00	20%
To Check Electrical Lighting Concerned.	\$	170.00	15%
To check steering geometry and computer wheel alignment	\$	220.00	60%
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	nn 170.00	X

TOTAL	\$	4,550.00
--------------	-----------	-----------------

Over All Total	\$	16,433.60
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days~~08 Days~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHB7833L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	17 Jul 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2C04280
Chassis No.:	JTDKB3FU703079633
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	29 Mar 2019
First Registration Date:	29 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Mar 2027
PARF Rebate Amount:	\$9,972.00

Intended COE Rebate Details

COE Expiry Date:	28 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$20,420.00
COE Rebate Amount:	\$6,882.00
Total Rebate Amount:	\$16,854.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Jul 2024

OK