

Not Authorized
1/Eng B

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7833L

AAD2407-066

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

10 JUL 2024

SHB7833L

JTDKB3FU703079633

200303878K

TOYOTA

PRIUS

16/7/2024

SHM 61862/China

29/3/2019

PART

- 1 COVER, FRONT BUMPER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 SUPPORT, FRONT BUMPER SIDE, LH
- 1 STAY SUB-ASSY, FRONT BUMPER, LH
- 1 MIRROR ASSY, OUTER REAR VIEW, LH
- 1 LINER, FRONT FENDER, LH
- 1 FENDER SUB-ASSY, FRONT LH
- 1 FRONT FENDER EMBLEM LH
- 1 RIM
- 1 LAMP ASSY, FOG, LH
- 1 UNIT ASSY, HEADLAMP, LH
- 1 MOULDING ASSY, BODY ROCKER PANEL, LH

LIST

\$	Bu	653.31	✓
\$	su	100.17	X
\$	R	902.16	X
\$	Dr	100.49	✓
\$	h	59.85	X
\$	n	1,695.65	X
\$	h	255.36	X
\$	By	1,236.69	✓
\$	m	68.88	✓
\$	nd	2,554.70	✓
\$	h	1,200.78	X
\$	h	3,325.56	X
\$	h	624.54	X

TOTAL \$ 12,778.14

25% \$ 3,194.53

\$ 9,583.60

Special Nett

- 1 TYRE
- 1SET CLIP, ROCKER PANEL MOULDING
- 1 FRT BUMPER CLIP
- 1SET FENDER CLIP
- 1 FENDER LINER CLIP

\$	h	350.00	X
\$	m	65.00	X
\$	m	65.00	dash
\$	m	130.00	X
\$	m	65.00	X

TOTAL \$ 675.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7833L**AAD2407-**

TOTAL PARTS	\$	2,300.00
--------------------	-----------	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	301
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	400
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	440
To transfer of tire, rim and on wheel balancing.	\$	170.00	201
To Check Electrical Lighting Concerned.	\$	170.00	151
To check steering geometry and computer wheel alignment	\$	220.00	601
To remove and refit of rear fender fittings, attachment and perform water seepage test.	\$	nn 170.00	X

TOTAL	\$	4,550.00
--------------	-----------	-----------------

Over All Total	\$	16,433.60
-----------------------	-----------	------------------

(PART-BY-PART) Repair Days~~08 Days~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: