

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CD/AIG24070312/KUA3Q2**Date:** 21/11/2025REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1900235650   |
| <b>Claimant Vehicle No :</b> | SKT9466U                             | <b>Insured Vehicle No :</b> | GBG9428E     |
| Date of Loss:                | 13/07/2024                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 8363648868SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                         |             |                   |
|-----------------------------|-----------------------------------------|-------------|-------------------|
| Reg No:                     | <b>SKT9466U</b>                         |             |                   |
| Make & Model:               | MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A) | Engine No:  | P520281337        |
| Reg. Date:                  | 26/06/2015 (Man. Year: 2015)            | Chassis No: | JM6BM42A8G0309952 |
| Colour:                     | Metallic Blue                           | Odometer:   | 162272 km         |
| Engine Capacity:            | 1496 cc                                 |             |                   |
| Market Value/New Car Price: | N/A                                     |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>       |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 205/60 R16    | Rear Tyre Size:  | 205/60 R16    |
| Front Left Side:  | Yokohama 7 mm | Rear Left Side:  | Yokohama 7 mm |
| Front Right Side: | Yokohama 7 mm | Rear Right Side: | Yokohama 7 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                                      | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|------------------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                                      | 1,702.24          | 1,491.04          | 211.20            | 12.41         |
| Miscellaneous Items                                        | 0.00              | 0.00              | 0.00              |               |
| Labour                                                     | 960.00            | 660.00            | 300.00            | 31.25         |
| Paintwork Labour                                           | 0.00              | 0.00              | 0.00              |               |
| Towing                                                     | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>                        | <b>2,662.24</b>   | <b>2,151.04</b>   | <b>511.20</b>     | <b>19.20</b>  |
| <b>Approved Total (Overridden) (S\$)</b>                   |                   | <b>1,650.00</b>   |                   |               |
| <b>(S\$)</b>                                               | 2,662.24          | 1,650.00          | 1,012.24          | 38.02         |
| <b>+ GST 9.00/9.00% (S\$)</b>                              | 239.60            | 148.50            | 91.10             | 38.02         |
| <b>Nett Amount (S\$)</b>                                   | <b>2,901.84</b>   | <b>1,798.50</b>   | <b>1,103.34</b>   | <b>38.02</b>  |
| <b>+ Car Rental (3.0 x S\$90.00/day + 9.00% GST) (S\$)</b> |                   | 294.30            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                              |                   | 2.18              |                   |               |
| <b>Nett Liability (S\$)</b>                                |                   | <b>2,094.98</b>   |                   |               |

INSPECTION

|                             |            |                                                                                                                      |
|-----------------------------|------------|----------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 15/08/2024 |                                                                                                                      |
| Date Inspected:             | 15/08/2024 | Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)<br>Blk 1019 #01-374/382, Yishun Industrial Park A<br>Singapore 768761 |
| Estimated Period of Repair: | 3.0 days   |                                                                                                                      |

**Adjuster:** KENNETH KONG**Manager:** NA MENG YAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                    | Condition   | Repairer's | Amount     |
|-----|-----|----------|--------------------------------|-------------|------------|------------|
| 1   | 1   |          | *REAR BUMPER                   | Cracked     | 998.00 FL  | *998.00 FL |
| 2   | 1   |          | *REAR BUMPER REINFORCEMENT     | Bent        | 576.00 FL  | *576.00 FL |
| 3   | 1   |          | *REAR BUMPER RH TOW HOOK COVER | Missing     | 18.80 FL   | *18.80 FL  |
| 4   | 6   |          | *REAR BUMPER CLIP              | Necessary   | 21.00 FL   | *21.00 FL  |
| 5   | 1   |          | *REAR BOOT INNER LOCK          | Repair      | 124.00 FL  | *- FL      |
| 6   | 1   |          | *REAR BOOT INNER RUBBER        | Serviceable | 140.00 FL  | *- FL      |
| 7   | 1   |          | *SET REVERSE SENSOR            | Scratched   | 200.00 FS  | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                 |                 |
|------------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>2,077.80</b> | <b>1,813.80</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 375.56          | 322.76          |
| <b>Total Parts (\$\$)</b>                                  | <b>1,702.24</b> | <b>1,491.04</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                             | Lab.Type | Repairer's    | Amount        |
|---------------------------------|-----------------------------------------------------------------------------------------|----------|---------------|---------------|
| <b>Labour Items</b>             |                                                                                         |          |               |               |
| 1                               | REMOVE & REFIX REAR BUMPER ASSY ,TO KNOCKING & REPAIR REAR END PANEL & REALIGN THE SAME | New      | 480.00        | 300.00        |
| 2                               | PUTTY & RESPRAY ON REAR BUMPER, REAR PANEL ,REAR REINFORCEMENT                          | New      | 480.00        | 360.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                         |          | <b>960.00</b> | <b>660.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >