



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)	Ref:	CS/SPF24070313/Aqp3
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)	Date:	14/08/2024
POLICE LOGISTICS BASE (PLB)	Code:	SPF
1 HEMMANT ROAD SINGAPORE 438675		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 374T	Veh. Inspected	SMD 6706H
Policy No.	-	Coverage	0
Claim No.	ACS/105/009/2024/028 (CF)	Excess	\$0.00
Assign From	LAI PENGCHONG	Assign Date	19/07/2024

2. Vehicle Details

Make & Model	B.M.W. 216I GT	C.C	1499
Engine No.	30025761B38A15A	Year of Reg.	31/10/2019
Chassis No.	WBA6V120205P06210	Colour	BLACK
Odometer	89710 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/45 R18	CONTINENTAL	6
L/H Front Tyre	225/45 R18	CONTINENTAL	6
R/H Rear Tyre	225/45 R18	CONTINENTAL	6
L/H Rear Tyre	225/45 R18	CONTINENTAL	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/07/2024	Inspection Date	24/07/2024
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days