

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24070315/EQP3E2**Date:** 17/12/2024REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR003131
Claimant Vehicle No :	SHB6617B	Insured Vehicle No :	SMT4851A
Date of Loss:	18/07/2024	Nature of Claim:	TP
		Claim No:	M2404044

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB6617B	Engine No:	G4LEKU296101
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU164494
Reg. Date:	10/07/2019 (Man. Year: 2019)	Odometer:	405755 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 4 mm	Rear Left Side:	West Lake 4 mm
Front Right Side:	West Lake 4 mm	Rear Right Side:	West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,511.92	3,617.08	894.84	19.83
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,040.00	970.00	70.00	6.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,563.92	4,599.08	964.84	17.34
Approved Total (Overridden) (\$\$)		3,700.00		
(\$\$)	5,563.92	3,700.00	1,863.92	33.50
+ GST 9.00/9.00% (\$\$)	500.75	333.00	167.75	33.50
Nett Amount (\$\$)	6,064.67	4,033.00	2,031.67	33.50

INSPECTION

Date of Assignment:	19/07/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	22/07/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang)
			59 Loyang Drive
			Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2024)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB6617B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Broken	481.10 FL	*481.10 FL
2	1		*FRT BUMPER UPPER MOULDING	Cut	368.50 FL	*368.50 FL
3	1		*RADIATOR GRILLE	Broken	1,409.10 FL	*1,409.10 FL
4	1		*RADIATOR GRILLE H EMBLEM	Not Necessary	492.00 FL	*- FL
5	10		*FRT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
6	1		*FRT BUMPER SIDE BRKT LH	Broken	35.00 FL	*35.00 FL
7	1		*HEADLAMP LH	Cut	2,110.30 FL	*2,110.30 FL
8	1		*FRT FENDER SHIELD LH	Not Necessary	164.70 FL	*- FL
9	10		*FRT FENDER SHIELD CLIPS LH	Not Necessary	22.00 FL	*- FL
10	1		*DAYLIGHT GRILLE LH	Not Necessary	93.45 FL	*- FL
11	1		*FRT NO.PLATE WITH TRIM COVER	Broken	55.00 F	*55.00 F
12	1		*FRT FENDER (BLUE-DRIVE) LH	Necessary	26.60 FL	*26.60 FL
13	1		*FRT WHEEL CAP LH	Not Necessary	346.40 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	5,626.15 4,507.60
					- List Item Discount on L Items 20.00/20.00% (\$\$)	1,114.23 890.52
					Total Parts (\$\$)	4,511.92 3,617.08

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (S\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	380.00
2	SPRAY PAINTING (FRT FENDER LH ETC)	New	600.00	560.00
3	CHECK LIGHTINGS	New	40.00	30.00
Gross Labour Cost (S\$)			1,040.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >