

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24070316/RNP3M4

Date: 10/10/2024

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002288157		
Claimant Vehicle No :	XE303R	Insured Vehicle No :	SFL207L		
Date of Loss:	16/07/2024	Nature of Claim:	TP	Claim No:	367074

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	XE303R	Engine No:	F3AE3681YU022182913
Make & Model:	IVECO STRALIS, 10.3 D AT440S46T/P EURO V 60T (A)	Chassis No:	WJMM1VTH4DC264298
Reg. Date:	30/01/2015 (Man. Year: 2013)	Odometer:	299713 km
Colour:	Red		
Engine Capacity:	10308 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	315/80R22.5	Rear Tyre Size:	315/80R22.5 (D)
Front Left Side:	366 8 mm	Rear Left Side:	366 8/8 mm
Front Right Side:	366 8 mm	Rear Right Side:	366 8/8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,695.00	5,892.28	9,802.72	62.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,770.00	1,200.00	570.00	32.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,465.00	7,092.28	10,372.72	59.39
Approved Total (Overridden) (S\$)		5,600.00		
(S\$)	17,465.00	5,600.00	11,865.00	67.94
+ GST 9.00/9.00% (S\$)	1,571.85	504.00	1,067.85	67.94
Nett Amount (S\$)	19,036.85	6,104.00	12,932.85	67.94

INSPECTION

Date of Assignment:	19/07/2024	
Date Inspected:	23/07/2024	Inspected At: R&S AUTOCLAIM PTE LTD (HQ) 13 PIONEER SECTOR 1, SINGAPORE 628424
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 30 Sep 2024)	
Parts:	N/A	IVECO STRALIS 10.3 D AT440S46T/P EURO V 60T (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for XE303R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	10,720.00 F	*4,286.98 FL
2	1		*FRONT BUMPER LOWER LH	Cracked	250.00 F	*250.00 FL
3	1		*FRONT BUMPER SIGNAL LAMP LH	Not Necessary	235.00 F	*- FL
4	1		*HEAD LAMP LH	Not Necessary	1,485.00 F	*- FL
5	1		*CORNER LAMP LH	Not Necessary	390.00 F	*- FL
6	1		*FOG LAMP LH	Not Necessary	260.00 F	*- FL
7	1		*STEP CENTRE LH	Scratched	95.00 F	*95.00 FL
8	1		*STEP LOWER LH	Missing	95.00 F	*95.00 FL
9	1		*STEP COVER LH	Cracked	1,865.00 F	*1,520.00 FL
10	1		*STEP SIDE SUPPORT BRACKET	Cut	300.00 F	*300.00 FL
					Sub Total (\$\$)	15,695.00 6,546.98
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 654.70
					Total Parts (\$\$)	15,695.00 5,892.28

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO STRAIGHTEN AND PANEL BEAT ON ACCIDENT LH AREA	New	900.00	600.00
2	TO PUTTY, RE-SPRAY PAINTING AND POLISHING ON ACCIDENT LH AREA	New	750.00	600.00
3	TO CHECK AND RECTIFY WIRING CONNECT AND DISCONNET	New	120.00	0.00
Gross Labour Cost (S\$)			1,770.00	1,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >