

[illegible]

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0567/2024/KS
DATE : 22-Jul-24
WIP : 24024

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 23/7/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR NG KIM ENG
ADDRESS : 67 BEGONIA DRIVE
SINGAPORE 809925
TELEPHONE : HP +65 96970099
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800108415-04
VEHICLE NO : **SME 1079 L**
MODEL CODE : A3 SEDAN 1.4 TFSI
MODEL YEAR : 18/9/2018
ENGINE NO : CZE 697799
CHASSIS NO : WAUZZZ8V4J1080560
MILEAGE : KM
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Jul-24
PLACE OF ACCIDENT : TAMPINES AVE 1

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SME 1079 L.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$	280.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAIL LIGHT.	S/N \$	280.00	X
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,450.00 500	
4	TO RESPRAY REAR BUMPER, REAR LID AND REAR END PANELLING.	\$	2,450.00 1100	
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	292.00	✓
TOTAL LABOUR CHARGES		: \$	5,752.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SME 1079 L.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Delid</i>	1	\$ 2,615.00	✓
2	REAR BUMPER STICKY PAD	4	\$ 30.00	+
3	REAR BUMPER FIXING PARTS	1	\$ 216.00	+
4	REAR BUMPER ADAPTOR - LH / RH	2	\$ 96.00	+
5	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 42.00	+
6	REAR BUMPER GUIDE SECTION PIN - LH / RH	2	\$ 75.00	+
7	REAR BUMPER SPOILER <i>Delid</i>	1	\$ 297.00	✓
8	REAR LIGHT REFLECTOR - LH / RH	2	\$ 98.00	+
9	REAR PARKING AID SENSOR	2	\$ 572.00	+
10	REAR PARKING AID SENSOR SEAL RING	4	\$ 11.00	+
11	REAR BUMPER REINFORCEMENT BEAM	1	\$ 736.00	+
12	REAR BUMPER BRACKET - LH / RH	2	\$ 74.00	+
13	REAR LID <i>Rejis</i>	1	\$ 4,085.00	+
14	REAR LID ATTACHMENT PARTS <i>Rejis</i>	1	\$ 329.00	+
15	REAR LID PACKING ADHESIVE <i>Rejis</i>	1	\$ 23.00	✓
16	REAR LID LOCK COVER	1	\$ 9.00	+
17	REAR LID LOCK	1	\$ 227.00	+
18	REAR LID WEATHER STRIP	1	\$ 255.00	+
19	AUDI EMBLEM <i>Rejis</i>	1	\$ 162.00	✓
20	"A3" EMBLEM	1	\$ 116.00	✓
SUB TOTAL SPARE PARTS		:	\$ 10,068.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SME 1079 L

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
41	"TFSI" EMBLEM <i>new</i>	1	\$ 116.00	✓
42	"ULTRA" EMBLEM <i>new</i>	1	\$ 116.00	+
43	SUNDRIES <i>?</i>	1	\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 10,800.00	
TOTAL LABOUR CHARGES		:	\$ 5,752.00	
GRAND TOTAL		:	\$ 16,552.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adnan Ly*
SURVEYED DATE : *23/07/24*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *we authorised, 04 days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT