

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 3152/07/24 Your Ref: Date: 22nd July 2024

MR NG CHUAN MING
BLK 442C, Bukit Batok West Ave S
#06-841, Singapore 653442

Estimate cost of repair to VOLKSWAGON POLO 1.2 (A) TSI H/B - SLS 6215 R

1 pc rear bumper		R \$ 840.00 X
1 pc rear bumper n/s side retainers reflector		cn 98.00
10 pcs rear bumper clips	6.50	11 65.00 X
		<u>\$ 1,003.00</u>
	Less 5%	\$ 50.15
		<u>\$ 952.85</u>

To wiring check up for affected wiring system. 50.00 20

To remove & refix carpet, floor board cover, floor mat, garnish, tool set, spare tyre & necessary parts. 11 120.00 X

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear n/s render & necessary parts, to weld, renew & align above parts. 500.00 200

To putty & respray painting on all affected accident parts. 650.00 300

\$ 2,272.85
=====

Dollars : Two Thousand Two Hundred Seventy Two And Cents Eighty Five Only.

HUP MOTOR TRADING & SERVICE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

not Allowed
my
23/7/24
217 \$ 613.10
2 Lyr.
the photo of the repair