

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. : SAC2401764

INV Date : 10-12-2024

Reference CD/LPC24070321/Uua3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLE 6228C
Insured Veh. GBJ 5708H
Claim No. 24/24/24/VC05/029570
Policy No.
Accident Date 18/07/2024
Inspection Date 01/08/2024

Description	Amount
Third Party Express Settlement	450.00
Sub-Total	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CD/LPC24070321/Uua3q2
300 BEACH ROAD	Date:	10/12/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	GBJ 5708H	Veh. Inspected	SLE 6228C
Policy No.	-	Coverage	0
Claim No.	24/24/24/VC05/029570	Excess	\$0.00
Assign From	ERIC WOO	Assign Date	22/07/2024

2. Vehicle Details

Make & Model	AUDI Q2 1.0 TFSI S TRONIC	C.C	999
Engine No.	CHZ330349	Year of Reg.	29/05/2017
Chassis No.	WAUZZZGA9HA034456	Colour	BLACK
Odometer	126131 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/50Z R18	LAND SPIDER	6
L/H Front Tyre	225/50Z R18	LAND SPIDER	6
R/H Rear Tyre	225/50Z R18	WESTLAKE	6
L/H Rear Tyre	225/50Z R18	WESTLAKE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/07/2024	Inspection Date	01/08/2024
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLE 6228C

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	O/S WING MIRROR	DAMAGED	\$1,657.50	\$1,190.00
1	O/S FRONT DOOR	DENTED	\$3,531.00	\$3,152.00
1	O/S FRONT DOOR RUBBER	NECESSARY	\$299.00	\$180.00
1	O/S FRONT DOOR BOARD	NOT NECESSARY	\$1,566.00	\$0.00
1	O/S FRONT DOOR PROTECTOR	BENT	\$433.50	\$303.50
1	O/S FRONT DOOR OUTER MOULDING	SERVICEABLE	\$198.00	\$0.00
1	O/S FRONT DOOR REGULATOR GEAR	NOT NECESSARY	\$540.00	\$0.00
1	O/S FRONT DOOR REGULATOR MOTOR	NOT NECESSARY	\$545.50	\$0.00
1	O/S FRONT DOOR GLASS	CUT	\$851.00	\$241.00
1	O/S FRONT FENDER ARCH GARNISH	GRAZED	\$445.50	\$445.50
	LESS 10.00% DISCOUNT		(\$1,006.70)	(\$551.20)
			\$9,060.30	\$4,960.80
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET O/S FRONT DOOR BOARD CLIP (SN)	NECESSARY	\$50.00	\$50.00
1	O/S FRONT DOOR GLASS SOLAR FILM (SN)	NECESSARY	\$250.00	\$180.00
1	SET O/S FRONT DOOR RIVETS (SN)	NECESSARY	\$50.00	\$30.00
			\$350.00	\$260.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK LIGHT AND WIRING		\$50.00	\$20.00
	TRANSFER DOOR PARTS		\$100.00	\$60.00
	TO DIAGNOSE AND CLEAR CODE		\$180.00	\$80.00
	LABOUR/PANEL BEATING		\$500.00	\$300.00
	SPRAY PAINTING		\$700.00	\$400.00
			\$1,530.00	\$860.00
GRAND TOTAL			\$10,940.30	\$6,080.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$4,800.00
Report Ref No: CD/LPC24070321/Uua3q2				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

MARKET VALUE: \$18,498.00(EST) LESS LTA REBATE: \$13,221.00(EST) = NETT VALUE :\$5,277.00(EST)

CKS



MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C




PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C



PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C



PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C



PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C



PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C



PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C



PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C




PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C



PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C



PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C




PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C





PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C



PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C



PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SLE 6228C

