



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070323/Uqh3
16 RAFFLES QUAY	Date:	20/09/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7328Z	Veh. Inspected	SNF 7966U
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24006310MFCT	Excess	\$0.00
Assign From	BETTY WONG	Assign Date	22/07/2024

### 2. Vehicle Details

Make & Model	BYD E6 (ME-2)	C.C	-
Engine No.	HIDDEN	Year of Reg.	23/06/2022
Chassis No.	LC0CE4DC1N0066127	Colour	WHITE
Odometer	231322 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/55ZR17	APLUS	6
L/H Front Tyre	215/55ZR17	APLUS	6
R/H Rear Tyre	215/55ZR17	APLUS	6
L/H Rear Tyre	215/55ZR17	APLUS	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	17/07/2024	Inspection Date	22/07/2024
Survey held at	CARSMITH PTE LTD – PREMIER@8 KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875		

### 5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days