

CARSMITH PRIVATE LIMITED
PREMIER@8KAKI BUKIT AVE 4 #04-35 SINGAPORE415875
 Tel: 9091 0000/ Email: info@carsmith.biz

*Not Authorized
 Mr. MORAIS
 22/7/24
 P/P \$23605.31
 8 days.*

SNF7966U
 VEHICLE NO: SNH6855C
 MAKE & MODEL: BYD E6
 DOA:
 CLAIM TYPE:

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
FRONT BONNET	1	\$ 2,695.68	Buc ✓
FRONT BONNET INSULATOR	1	\$ 565.00	11 X
FRONT BONNET LOCK	1	\$ 475.00	7M ✓ 162
FRONT BONNET HINGE	2	\$ 290.00	11 X
FRONT BUMPER	1	\$ 3,062.40	Dis ✓ 1658
FRONT BUMPER RETAINER LH	1	\$ 79.00	Bnt ✓
FRONT BUMPER RETAINER RH	1	\$ 79.00	Bnt ✓
FRONT BUMPER BRACKET LH	1	\$ 79.00	11 X
FRONT BUMPER BRACKET RH	1	\$ 79.00	11 X
FRONT BUMPER CENTER CHROME	1	\$ 825.00	CN ✓ 385
FRONT BUMPER LOWER GRILLE	1	\$ 275.00	Torn ✓
FRONT BUMPER LOWER GRILLE LH	1	\$ 285.00	11 X
FRONT BUMPER LOWER GRILLE RH	1	\$ 285.00	11 X
FRONT REINFORCEMENT	1	\$ 668.00	Bnt ✓ 485
FRONT SUPPORT PANEL	1	\$ 1,785.00	CN ✓ 1100
FRONT HEADLAMP LH	1	\$ 3,250.00	CN ✓ 2600
FRONT HEADLAMP PANEL LH	1	\$ 325.00	Bnt ✓ 190
FRONT HEADLAMP BRACKET LH	1	\$ 179.00	11 X
FRONT HEADLAMP RH	1	\$ 3,250.00	CN ✓ 2600
FRONT HEADLAMP PANEL RH	1	\$ 325.00	Bnt ✓ 190
FRONT HEADLAMP BRACKET RH	1	\$ 179.00	11 X
AIR GUIDE LH	1	\$ 105.00	11 X
AIR GUIDE RH	1	\$ 105.00	11 X
AIR GUIDE TOP	1	\$ 105.00	11 X
AIR GUIDE BOTTOM	1	\$ 105.00	11 X
BATTERY	1	\$ 250.00	11 X
HORN	1	\$ 180.00	CN ✓ 150
RADIATOR	1	\$ 1,340.00	Bnt/pur ✓ 980
CONDENSER	1	\$ 1,800.00	Bnt/pur ✓ 1300
FAN MOTOR	1 SET	\$ 1,786.50	CRA RM ✓ 1650
WIPER TANK	1	\$ 275.00	11 X
WIPER MOTOR	1	\$ 355.00	11 X
WIPER BLADE	1	\$ 128.00	11 X
WIPER GARNISH	1	\$ 455.00	11 X
FRONT FENDER LH	1	\$ 2,550.00	Buc ✓ 1255
FRONT FENDER INNER SHIELD LH	1	\$ 528.00	11 X
FRONT FENDER RH	1	\$ 2,550.00	Buc ✓ 1255
FRONT FENDER INNER SHIELD RH	1	\$ 528.00	Torn ✓ 320
WINDSCREEN	1	\$ 2,830.00	11 X
WINDSCREEN MOULDING	1	\$ 528.00	11 X
FRONT DOOR RH	1	\$ 3,628.00	2 X
FRONT DOOR LH	1	\$ 3,628.00	11 X
REAR BUMPER	1	\$ 2,985.00	Dis ✓ 1650
REAR BUMPER RETAINER LH	1	\$ 98.00	11 X
REAR BUMPER BRACKET LH	1	\$ 98.00	Bnt ✓
REAR BUMPER BRACKET RH	1	\$ 98.00	Bnt ✓
REAR BUMPER GRILLE BAR LH	1	\$ 105.00	Torn ✓

REAR BUMPER GRILLE BAR CENTER	1	\$	144.00	10-1 ✓
REAR REFLECTOR LH RH	1	\$	198.00	B20 ✓ 125
REAR REFLECTOR CENTRE	1	\$	425.00	B20 ✓ 280
REAR END PANEL	1	\$	852.00	R X
REAR END PANEL TOP GARNISH	1	\$	287.00	11 X
REAR REINFORCEMENT	1	\$	565.00	B20 ✓ 383
REAR REINFORCEMENT BRACKET LH	1	\$	352.00	B20 ✓ 250
TAILGATE	1	\$	5,459.40	R X
TAILGATE LOGO	1	\$	108.00	11 X
TAILGATE EMBLEM 'BYD E6'	1	\$	108.00	11 X
TAILGATE CHROME MOULDING	1	\$	345.00	11 X
TAILGATE LOCK	1	\$	578.00	11 X
TAILGATE WEATHERSTRIP	1	\$	373.00	11 X
TAILGATE HINGE	2	\$	176.00	11 X
TAILGATE SENSOR	1	\$	528.00	11 X

rear bumper lower

DIS 9242 ✓

\$ 56,676.98
 LESS 10% \$ 5,667.70
SUB TOTAL \$ 51,009.28

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
FRONT NUMBER PLATE	1 SET	\$ 90.00	B20 40
FRONT BUMPER CLIP	1 SET	\$ 50.00	11 30
FRONT FENDER INNER SHIELD CLIP	2 SET	\$ 100.00	11 X
REAR BUMPER CLIP	1	\$ 200.00	11 30
REAR NUMBER PLATE	1SET	\$ 90.00	11 X
COOLANT	1	\$ 120.00	11 30
WINDSCREEN SEALANT	1	\$ 100.00	11 X
JOINT SEALANT	1	\$ 100.00	11 X

1 set Rear bumper sensor malfunction 200 S/N

SUB TOTAL \$ 850.00

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK FRONT WIRING AND LIGHTING SYSTEM	1	\$ 200.00	30
REMOVE AND REFIT FRONT DRIVER SEAT AIRBAG	1	\$ 550.00	11 X
REMOVE AND REFIT RADIATOR	1	\$ 150.00	11 X
RESET FAULT CODE FOR AIRBAG CONTROL MODULE	1	\$ 800.00	11 X
REMOVE AND REFIT FRONT WINDSCREEN	1	\$ 300.00	11 X
refill air-con gas	1	\$ 200.00	100
REMOVE AND REFIT FRONT ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH	1	\$ 450.00	60

PANEL BEATING ON AFFECTED AND RENEW DAMAGE PARTS	1	\$ 2,000.00	1000
SPRAY PAINTING ON AFFECTED AREAS	1	\$ 2,000.00	1500
APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	80
SUB TOTAL		<u>\$ 6,750.00</u>	
GRAND TOTAL		<u>\$ 58,609.28</u>	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-22783-68

102

P-20505-31

S.N - 330

L-2770

23605-31