

REPAIR ESTIMATE

Claim Type: Third Party Claim Date : 11 Jun 2024
 Attn: MS First Capital Insurance Limited Vehicle Num : SLD2704B
 Motor Claims Department Make/Model : TOYOTA HARRIER 2.0 A
 Owner: NAM SEA YONG Chassis # : ZSU600072441
 DOA: 06/06/2024 1 Engine # : 3ZRB729377
 Yr. Of Manu : 2015/2016

*not Authorised
 Mr
 Moray
 the ph. After up -*

No.	Description	Qty	U/P	Amt
-----	-------------	-----	-----	-----

Section: LIST ITEMS

1	Rear Door RH	1	S\$ 850.00 S\$	850.00 X
---	--------------	---	----------------	----------

Amt S\$ 850.00

DISCOUNT: 25% S\$ 212.50

Subtotal S\$ 637.50

No.	Description	Qty	U/P	Amt
-----	-------------	-----	-----	-----

Section: LABOUR

2	TO RE-SPRAY PAINTING ON THE CHANGE BODY PARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		S\$ 500.00	100
---	--	--	------------	-----

3	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		500.00	200
---	--	--	--------	-----

4	REMOVE, REINSTALL, AND REPLACE REAR RH DOOR INNER MECHANISM TO ASSIST REPAIR		120.00	X
---	--	--	--------	---

Amt S\$ 1120.00



Joo Hak Kee Auto Pte. Ltd.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LIST ITEMS Subtotal: S\$ 637.50

LABOUR Subtotal: S\$ 1,120.00

Total: S\$ 1,757.50