

ASSIGNMENT

Front: _____ Date: _____

Estim: _____

OD / ~~TP~~ / TP RES / OD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at _____

of _____

Insured: _____

Policy: _____

Claims: _____

Sum Insured: _____ Excess: _____

(Client Record)

Make of Vehicle: _____

(Policy Condition)

N/S	O/S

Remark: Vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMX5566X Yr Regn: 2016 August

Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz C.D. 1498

Colour: Orange A/C: Insured / Std / NI / NA

Sp. Reading: 225671 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHMGK5850HX200080

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 15/07/24

Survey held at HD Perfect

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP China

COE Expiry

Estimate given during: Yes ☒
1st Survey: No ☒

MV: 34K

PV: 18.3K

Nett: 15.7K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

3 + RS. \$1

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Inve (\$

Report Form:

Report Form:


HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 15.07.2024

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SMX5566X
MODEL : HONDA JAZZ
DATE OF ACCIDENT : 23.06.2024
TIME OF ACCIDENT : 13:20 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dehd</i>	1	\$ 710.30	\$ 710.30
2	REAR BUMPER SIDE COVER GARNISH <i>new</i>	2	\$ 24.10	\$ 48.20
3	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 35.20	\$ 70.40
4	TAIL LAMP <i>new LH outer new</i>	2	\$ 247.70	\$ 495.40
5	REAR FENDER INNER COWLING <i>new</i>	2	\$ 78.10	\$ 156.20
6	REAR FENDER INNER TRIM <i>new</i>	2	\$ 298.90	\$ 597.80
7	TAIL GATE <i>Dented</i>	1	\$ 984.90	\$ 984.90
8	TAIL GATE LOGO <i>new</i>	1	\$ 24.70	\$ 24.70
9	TAIL GATE EMBLEM 'JAZZ' <i>new</i>	1	\$ 39.40	\$ 39.40
10	TAIL GATE OUTER MOULDING <i>new</i>	1	\$ 197.10	\$ 197.10
11	TAIL GATE WINDSCREEN MOULDING <i>new</i>	2	\$ 76.00	\$ 152.00
12	TAIL GATE DAMPER <i>new</i>	2	\$ 104.70	\$ 209.40
13	TAIL GATE INNER HOLDER <i>new</i>	1	\$ 32.10	\$ 32.10
14	TAIL GATE STOPPER <i>new</i>	2	\$ 15.20	\$ 30.40
15	TAIL GATE INNER LOCK <i>Dented</i>	1	\$ 169.40	\$ 169.40
16	TAIL GATE LOCK CATCH <i>new</i>	1	\$ 25.00	\$ 25.00
17	TAIL GATE WEATHER STRIP <i>new</i>	1	\$ 134.50	\$ 134.50
18	TAIL GATE INNER TRIM <i>new</i>	1	\$ 246.20	\$ 246.20
19	TAIL GATE BUZZER <i>new</i>	2	\$ 134.10	\$ 268.20
20	TAIL GATE DETECTOR <i>new</i>	1	\$ 347.60	\$ 347.60
21	REAR END PANEL <i>Dented</i>	1	\$ 396.80	\$ 396.80
22	REAR END PANEL TOP GARNISH <i>Dehd</i>	1	\$ 116.20	\$ 116.20

495

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SMX5566X
 MODEL : HONDA JAZZ
 DATE OF ACCIDENT : 23.06.2024
 TIME OF ACCIDENT : 13:20 HOURS

TOTAL PRICE \$ 5,452.20
 LESS 20% \$ 1,090.44
 SUB TOTAL PRICE \$ 4,361.76

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	REAR BUMPER SIDE COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
4	TAIL GATE SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
5	TAIL GATE OUTER MOULDING CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
6	TAIL GATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
7	TAIL GATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
8	TAIL GATE WINDSCREEN INNER SEAL <i>new</i>	1	\$ 60.00	\$ 60.00
9	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
10	REAR FENDER INNER COWLING (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
11	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
12	REAR END PANEL INSUALTION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00
13	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 40.00	\$ 40.00

TOTAL \$ 870.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	700
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	700
3	TUFF COAT	\$ 250.00	60
4	WIRING CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00	60
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50

TO : CHINA TAIPIING MOTOR CLAIMS DEPTS
 VEHICLE NO : SMX5566X
 MODEL : HONDA JAZZ
 DATE OF ACCIDENT : 23.06.2024
 TIME OF ACCIDENT : 13:20 HOURS

8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
9	TRANSFER TAILGATE MECHANISM	\$ 80.00	60
10	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x.
11	REMOVE AND REFIX VIDEO CAMERA	\$ 120.00	50
12	TO CHECK DIANOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL \$ 4,620.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,231.76
 TOTAL LABOUR COST : \$ 4,620.00
 TOTAL REPAIR COST : \$ 9,851.76

Adrian
 h/s 15/07/24
 OG Rys

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: